

Contract No. FA64WA-5223

IBM 9020D/E DATA PROCESSING SYSTEM

FOR

UNITED KINGDOM 9020 TRIPLEX

FIELD ACCEPTANCE TEST REPORT

FOR

ITEMS TESTED IN AMENDMENT 88

January 28, 1974 - January 31, 1974

This information is furnished in accordance with requirements of Contract No. FA64WA-5223 and is subject to Clause 24 thereof entitled, "Reproduction and Use of Technical Data" which provides for its use, reproduction or disclosure by the Government for Government purposes.

INTERNATIONAL BUSINESS MACHINES CORPORATION

## CONTENTS

CONTENTS	ii
INTRODUCTION	1
ACCEPTANCE TEST SUMMARY	1
QUALITY CONTROL COMMENTS	3
EC/REA STATUS	3
EQUIPMENT IDENTIFICATION LIST	4
SPECIAL FEATURES AND RPQs	9
DELIVERABLE ITEMS LIST	13
FIELD FLOOR LAYOUT	15
9020D/E SYSTEM TEST LOGS AND RECORDS	17

## INTRODUCTION

The Field Acceptance Test for the United Kingdom 9020 Triplex System was conducted from January 28, 1974 thru January 31, 1974. The test was run in accordance with the concurred upon Test Check List entitled, "IBM 9020D/E System Acceptance Test Check List" and "IBM 9020D/E Data Processing Factory and Field Acceptance Test Specification - Revision 7."

All tests that were scheduled to be performed as a part of the Acceptance Test were completed successfully.

The errors encountered during this test are placed into the following categories:

1. Transient Failure - an error which does not recur upon repeated runs of the same routine.
2. Malfunction - an error which recurs upon repeated runs of the same routine or, in the case of the SEVA exercise, the same error occurring on successive passes of the program.

During the Field Acceptance Test, ten (10) malfunctions and nine (9) transients occurred.

## ACCEPTANCE TEST SUMMARY

The Field Acceptance Test consisted of Element Manual Tests, Element Subsystem and System Functional tests. At the completion of the System Functional Tests, at 0020 time on January 30, 1974, the United Kingdom 9020D Triplex System was placed in Idle and Order. At 2235 time of the same day the system was removed from this code and the Element Manual Test (U-021) and Element Subsystem Test (U-139) was conducted on the additional Printer/Keyboards (1052-07).

During the Element Subsystem Functional Tests five (5) malfunctions and two (2) transients were encountered. These failures are described as follows:

- |      |   |
|------|---|
| M-01 | Test U-106 IOCE #1 failure occurred while running IOCE #1 Selector Channel #2. D-3152 with Tape Drive #221. Data Read errors required off-line maintenance for Tape Drive #221. Reruns were completed successfully. |
| M-02 | Test U-114 Tape Drive #521 Write errors while running D4060. Corrective action required replacement of Capstan Motor P/N 5391708. Reruns were completed successfully.   |

- M-03 Test U-127 SE #6 picking and dropping bits randomly in high/even BSM. Corrective action required replacement of Card P/N 5804957 at location 03A-B1C4. Reruns were completed successfully.
- M-04 Test U-135 PAM #1 Unit Check while running INTO adapter "1B". Bit #6 picking. Corrective action required reseating card at location H-D1F2. Reruns were completed successfully.
- M-05 Test U-127 SE #5 Storage Logout problem. Corrective action required replacement of Card P/N 5803358 at location 03C-C2H2. Reruns were completed successfully.
- T-01 Test U-112 Tape Drive #112 Unit Check on write operation.
- T-02 Test U-116 Tape Drive #932 Unit Check on write operation.

During the System Functional Tests one (1) malfunction and two (2) transients occurred. These failures are described as follows:

- M-07 Test S-160 SE #1 picking bit #46 low/odd BSM. Corrective action required replacing Card P/N 5801708 at location 03A-A3F6. All elements were configured into the active system for two passes of SEVA.
- T-02 Test S-003 CE #2 would not clear DAR bit for CE own and IOCE #3.
- T-09 Test S-131 PAM #1 configured State Zero test switch on, during the Power Interlock test dropped power by means of the Power On/Off switch.

During the twelve-hour System Evaluation Program (SEVA) one (1) malfunction and five (5) transients occurred. These failures are described as follows:

- M-06 Test S-101 Tape Drive #221 indicated condition code #1. Corrective action required replacement of Prolay Assembly P/N 528540. After corrective action this unit was placed into the active system at pass 2E and reruns were successful.
- T-04 Test S-101 CE #1 Machine Check Interrupt, ROS Parity error Bits 66-99.
- T-05 Test S-101 Tape Drive #933 indicated a read error while reading from the System Load Tape.
- T-06 Test S-101 DSU #3 indicated a data check on drive #950.

T-07 Test S-101 SE #2 Data Error, Bytes 2 and 3 indicated incorrect parity.

T-08 Test S-101 DSU #2 indicated seek check on drive #560.

During the Element Test and Element Subsystem Test for the additional Printer/Keyboards (1052-07) three (3) malfunctions occurred. These failures are described as follows:

M-08 Test U-139 1052-07 S/N 30141 Jammed space key. Corrective action required adjustment of the key bar. Reruns were completed successfully.

M-09 Test U-139 1052-07 S/N 30138 Equipment Checks required adjustment of the carriage return contact. Reruns were completed successfully.

M-10 Test U-021 1052-07 S/N 30069 blowing fuses in the 48v line from PAM #1. Corrective action required removing a piece of wire shorting two contacts. Reruns were completed successfully.

#### QUALITY CONTROL COMMENTS

A quality control inspection was performed by the FAA Test Directors at the conclusion of the Acceptance Test. The discrepancies noted are listed in a separate letter forwarding this report.

#### EC/REA STATUS

There were no pending EC/REAs as of this Acceptance Test.

---

**EQUIPMENT IDENTIFICATION LIST**

# IBM EQUIPMENT IDENTIFICATION LIST

Location United Kingdom 9020D Triplex

Date 31-1-74

EQUIPMENT NAME	MODEL NO.	POSITION/ ADDRESS	SERIAL NO.	
Integrated Control Unit	2821-01	1	18869	
	2821-02 ✓	2	24095	
Compute Element	7201-02 ✓	1	50050	
		2	50051	
		3	50052	
Input/Output Control Element	7231-02 ✓	1	11084	
		2	11085	
		3	11086	
Storage Element	7251-09 ✓	1	51986	
		2	51987	
		3	51988	
		4	51989	
		5	51990	
		6	51991	
		7	51992	
System Console	7265-02 ✓	1	65025	
Tape Control Unit	2803-01 ✓	1	12227	
		2	12228	
		3	12229	
Peripheral Adapter Modules Adapters	7289-02 ✓	1	89072	
				20 CD
				7 TTY
				6 FDEP
				3 GPI
				26 GPO
				7 1052
				5 INTI
				5 INTO

CONTRACT #FA64WA-5223

AMENDMENT	ITEM	AMENDMENT	ITEM
147	213, 213.1 29 a+e		

Approval Gordon L. Hurst Date 31/1/74

# IBM EQUIPMENT IDENTIFICATION LIST

Location United Kingdom 9020D Triplex

Date 31-1-74

EQUIPMENT NAME	MODEL NO.	POSITION/ ADDRESS	SERIAL NO.
Peripheral Adapter Modules Adapters: 20 CD 6 TTY 5 FDEP 2 GPI 27 GPO 7 1052 5 INTI (B) 5 INTO (B)	7289-02 ✓	2	89073
Peripheral Adapter Modules Adapters 20 CD 7 TTY 5 FDEP 3 GPI 27 GPO 7 1052 4 INTI (B) 4 INTO (B)	7289-02 ✓	3	89074
Storage Control Unit	2314-A1 ✓	1 2 3	19271 19272 19273
Disk Storage Unit	2312-A1 ✓	1-1 2-1 3-1	17253 17254 17255
Reader/Punch	2540-01 ✓		23054
Printer	1403-02 ✓	1 2	21332 21333

CONTRACT #FA64WA-5223

AMENDMENT	ITEM	AMENDMENT	ITEM
147	213, 213.1 29 a+e		

Approval Gordon L. Hunt Date 31/1/74



# IBM EQUIPMENT IDENTIFICATION LIST

Location United Kingdom 9020D Triplex

Date 31-1-74

EQUIPMENT NAME	MODEL NO.	POSITION/ ADDRESS	SERIAL NO.
Printer/Keyboard	1052-07 ✓		30069 ✓ 30125 ✓ 30128 ✓ 30133 ✓ 30135 ✓ 30137 ✓ 30138 ✓ 30139 ✓ 30140 ✓ 30141 ✓ 30142 ✓ 30143 ✓ 30144 ✓ 30145 ✓ 30146 ✓
Tape Drives (all 9-Track)	2401-03 ✓		36000 ✓ 36001 ✓ 36002 ✓ 36003 ✓ 36004 ✓ 36005 ✓ 36006 ✓ 36007 ✓ 36011 ✓ 36012 ✓ 36013 ✓ 36014 ✓ 36015 ✓ 36016 ✓

CONTRACT #FA64WA-5223

AMENDMENT	ITEM	AMENDMENT	ITEM
147	213, 213.1 29 ate		

Approval Gordon L. Heist Date 31/1/74

# IBM EQUIPMENT IDENTIFICATION LIST

Location United Kingdom 9020D

Triplex

Date 31-1-74

EQUIPMENT NAME	MODEL NO.	POSITION/ ADDRESS	SERIAL NO.
Disk Pack	2316-01 ✓		OD9505 OD9506 OD9507 OD9508 OD9509 OD9510 OD9511 OD9512 OD9513 OD9514 OD9515 OD9516 OD9517 OD9518 OD9519

CONTRACT #FA64WA-5223

AMENDMENT	ITEM	AMENDMENT	ITEM
147	213, 213.1 29 a+e		

Approval Gordon L. Hunt Date 31/1/74

**SPECIAL FEATURES AND RPQ LIST**

SPECIAL FEATURES AND RPQs INSTALLED ON THE UNITED KINGDOM 9020D TRIPLEX (cont)

Tape Unit Control

2803-A01

RPQ F12928 Switching to IOCEs

Direct Access Storage Facility

2314-A01

RPQ FA0418 Configuration Control Modification to 2314A1  
for connection to 9020A and 9020D

Feature 8170 Two Channel Switch

Integrated Control Unit

2821-01

Feature 8637 Universal Character Set Adapter

Integrated Control Unit

2821-02

Feature 8637 Universal Character Set Adapter

Feature 8100 Two Channel Switch

Printer/Keyboard (Local)

1052-07

Feature 9572 Extended BCD Code Print Element

Feature 9104 10 Characters/Inch Horizontal Spacing

Feature 9509 Pin Feed Platen

Feature 9162 Line Spacing 6 LPl, 13-1/8" Hole-to-Hole Width

RPQ F13197 Cable and Power on Indicator

RPQ F14713 Single Enter and Cancel Keys

Feature 9903 208V 60Hz

Printer/Keyboard (Remote)

1052-07

Feature 9104 10 Characters/Inch Horizontal Spacing

Feature 9509 Pin Feed Platen

Feature 9162 Line Spacing 6 LPl, 13-1/8" Hole-to-Hole Width

RPQ F13197 Cable and Power On Indicator

RPQ F14713 Single Enter and Cancel Keys

RPQ FDO674 Extended Cable for 1052 (one only-one time charge item 29e)

IBM 9020D/E DATA PROCESSING SYSTEM

SPECIAL FEATURES AND RPQs INSTALLED ON THE UNITED KINGDOM 9020D TRIPLEX

The following features and/or RPQs are installed on each of the units listed below:

Compute Element

7201-02

RPQ FA0416 CCR/DAR Modification for 2314A1 Connection to 9020D  
RPQ F30767 Wrap Bus Modification  
RPQ FB0140 Convert and Sort Symbols/Convert Weather Lines

Input/Output Control Element

7231-02

RPQ F16374 Address Translation  
RPQ F27112 Expanded Addressing  
RPQ F21241 Processor Mode  
RPQ F20974 Storage Element (64K) Interface Mod.

System Console

7265-02

RPQ F16378 Single Enter-Cancel Keys  
RPQ F16379 Patch Panel and Adapter Unit  
RPQ F20421 SMMC Interface Mod.  
RPQ F16373 Fourth CE Modification  
RPQ FA0417 Configuration and State Display Modification for  
2314A1 Connection to 9020D

Peripheral Adapter Module

7289-02

RPQ F26474 Power Mod.  
RPQ F19673 Two Level Shared Priority  
RPQ FA1771 Power Mod. 1052  
RPQ EE2682 Teletype End of Message

SPECIAL FEATURES AND RPQs INSTALLED ON THE UNITED KINGDOM 9020 TRIPLEX (cont)  
Printer/Keyboard (Remote) Contd

Feature 2814 235V 50Hz  
RPQ EE2260 CAA Print Element (one time charge item 29 a -  
no charge on remaining items)  
RPQ EE2259 Keypoint Change (Reference QC deficiency letter)

P

Printer

1403-02

Feature 8641 Universal Character Set  
Feature 4740 Interchangeable Chain Cartridge Adapter  
Feature 9631 PN-2 Print Arrangement (2 each) (1 AT CENTRE)

P

Approval: Gordon L. Hurst  
Date: 31/1/74

**DELIVERABLE ITEMS LIST**

IBM 9020D/E DATA PROCESSING SYSTEM DELIVERABLE ITEM LIST

UNITED KINGDOM 9020D TRIPLEX

MAINTENANCE DIAGNOSTIC PROGRAMS

CERTIFICATION

1	Set Internal Specifications (Writeups, Flowcharts)	<u>WL</u>
1	Set Program Listing	<u>WL</u>
1	Reel Program Library Tape	<u>WL</u>
1	Set Program Object Deck	<u>WL</u>
5	Reels FLT Tapes	<u>WL</u>
2	Sets SCOPEX	<u>WL</u>

ACCEPTANCE TEST PROGRAMS

1	Set Internal Specifications (Writeups, Flowcharts)	<u>WL</u>
1	Set Program Listings	<u>WL</u>
1	Reel Program Library Tape	<u>WL</u>
<u>2</u>	Reels FLT Tapes (3 for 9020E - 2 for 9020D)	<u>WL</u>

INSTRUCTION BOOKS (FE MANUALS)

1	Set Instruction Manuals <i>Reference Q.C. Letter</i>	<u>WL</u>
1	Set Automated Logic Diagrams Manuals	<u>WL</u>
1	Set Illustrated Parts Catalogs <i>Reference Q.C. Letter</i>	<u>WL</u>

MAGNETIC TAPE - CUSTOMER REEL 14 REELS  
(One reel supplied with each new tape drive.)



WL

Approval: Gordon L. Hurst

Date: 31/1/74



**FIELD FLOOR DIAGRAM**



UNITED KINGDOM 9020 TRIPLEX

9020D/E ACCEPTANCE TEST LOG AND RECORDS

ACCEPTANCE TEST LOG

						FAILURE DATA			TEST RECORD NO.	COMMENTS	OPERATOR
DATE	TIME		USAGE	OPER	UNIT OR	SERIAL	TYPE				
DA MO YR	START	STOP	CODE	CODE	ELEMENT	NO.	NO.	NO.			
28 01 74	0855	1105	UT	S				U-001		A. J. Remy	
28 01 74	0855	1205	UT	S				U-002	See comment on Test Data Record Sheet	A. J. Remy	
28 01 74	0855	1140	UT	S				U-003		A. J. Remy	
28 01 74	0855	1142	UT	S				U-004		A. J. Remy	
28 01 74	0855	0901	UT	S				U-013		A. J. Remy	
28 01 74	0901	0930	UT	S				U-014		A. J. Remy	
28 01 74	0930	1009	UT	S				U-018		A. J. Remy	
28 01 74	1010	1040	UT	S				U-019		A. J. Remy	
28 01 74	1040	1115	UT	S				U-020		A. J. Remy	
28 01 74	1120	1150	UT	S				U-021	Test completed on four local 1052's. The fourth is a spare being tested on RAM adapter address x3c. The remote 1052's will be tested upon completion of the Triplex test.	A. J. Remy	
28 01 74	1125	1200	UT	S				U-017		A. J. Remy	
28 01 74	1145	1245	UT	S				U-006		A. J. Remy	
28 01 74	1205	1240	UT	S				U-007		A. J. Remy	
28 01 74	1245	1305	ID						Lunch Break!	A. J. Remy	
28 01 74	1305	1353	UT	S				U-101		A. J. Remy	
28 01 74	1310	1353	UT	S				U-103		A. J. Remy	
28 01 74	1337	1420	UT	OE				U-102	Section sense switch "φ" entered in error.	A. J. Remy	
28 01 74	1353	1430	UT	S				U-105		A. J. Remy	
28 01 74	1357	1442	UT	DF	723102	11084	M-01	U-106	Failure running LOCK-1 selector channel 2.	A. J. Remy	
28 01 74	1400	1420	UT	S				U-108		A. J. Remy	

18

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION										
MALFUNCTION RECORD						USAGE CODES			OPERATION CODES	
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL
28	01	74	01	A. J. Remy	A. J. Remy	28/01/74	ST	SYSTEM TEST	DF	DETECTED FAILURE
							FE	FACTORY EXERCISE	PF	PROGRAM FAILURE
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE
							SU	SETUP TIME	XF	EXTERNAL FAILURE
							SM	SCHED. MAINT.	OE	OPERATOR ERROR
							UM	UNSCHED. MAINT.		
							FM	FACT. EXER. MARG.		

APPROVAL A. Hurst

DATE 28/1/74

# ACCEPTANCE TEST LOG

DATE		TIME		USAGE	OPER	FAILURE DATA			TEST RECORD NO.	COMMENTS	OPERATOR	
DA	MO	YR	START	STOP	CODE	CODE	UNIT OR ELEMENT	SERIAL NO.				TYPE NO.
28	01	74	1425	1445	UT	S				U-111	A. J. Remy	
28	01	74	1425	1448	UT	S				U-102	A. J. Remy	
28	01	74	1430	1447	UT	S				U-107	A. J. Remy	
28	01	74	1445	1505	UT	DF	TD112	36002	T-01	U-112	Unit check on Write - rerun successful.	A. J. Remy
28	01	74	1447	1508	UT	S				U-110	A. J. Remy	
28	01	74	1442	1448	UM					U-106	IocE-1 in unscheduled maintenance for M-01.	A. J. Remy
28	01	74	1448	1458	UT	S				U-106	A. J. Remy	
28	01	74	1505	1520	UT	S				U-112	A. J. Remy	
28	01	74	1510	1520	UT	DF	TD521	36004	M-02	U-114	Unit check on Write - rerun unsuccessful.	A. J. Remy
28	01	74	1520	2350	UM					U-114	TD521 in unsheduled maintenance for M-02.	A. J. Remy
28	01	74	1540	1558	UT	S				U-109	A. J. Remy	
28	01	74	1543	1555	UT	DF	TD932	36012	T-02	U-116	Unit check on Write - rerun successful.	A. J. Remy
28	01	74	1543	1620	UT	S				U-117	A. J. Remy	
28	01	74	1553	1640	UT	DF	SE-6	51991	M-03	U-127	Unexpected element check - rerun unsuccessful.	A. J. Remy
28	01	74	1555	1620	UT	S				U-116	A. J. Remy	
28	01	74	1558	1715	UT	S				U-126	A. J. Remy	
28	01	74	1620	1650	UT	S				U-128	A. J. Remy	
28	01	74	1654	1730	UT	DF	PAM-1	89074	M-04	U-135	Unit check while running INTO "1B"	A. J. Remy
28	01	74	1640	1715	UM					U-127	SE-6 in unscheduled maintenance for M-03	A. J. Remy
28	01	74	1715	1725	UT	DF	SE-5	51990	M-05	U-127	SE-6 rerun successfully, SE-5 layout failure.	A. J. Remy
28	01	74	1755	1815	UM					U-127	SE-5 in unscheduled maintenance for M-05.	A. J. Remy
28	01	74	1730	1755	UM		PAM-1	89074	M-04	U-135	PAM-1 in unscheduled maintenance for M-04.	A. J. Remy
28	01	74	1755	1935	UT	S				U-135	INTO "1B" rerun successfully.	A. J. Remy
28	01	74	1813	1845	UT	S				U-144	A. J. Remy	

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION

MALFUNCTION RECORD						USAGE CODES		OPERATION CODES		
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL
28	01	74	02	A. J. Remy	M. Malin	28/01/74	ST	SYSTEM TEST	DF	DETECTED FAILURE
28	01	74	03	A. J. Remy	A. J. Remy	28/01/74	FE	FACTORY EXERCISE	PF	PROGRAM FAILURE
28	01	74	04	A. J. Remy	A. J. Remy	28/01/74	ID	IDLE IN ORDER	MF	MATERIAL FAILURE
28	01	74	05	A. J. Remy	A. J. Remy	28/01/74	SU	SETUP TIME	XF	EXTERNAL FAILURE
							SM	SCHED. MAINT.	OE	OPERATOR ERROR
							UM	UNSCHED. MAINT.		
							FM	FACT. EXER. MARG.		

APPROVAL A. Hurst  
 DATE 29/1/74

							FAILURE DATA					
DATE			TIME		USAGE	OPER	UNIT OR	SERIAL	TYPE	TEST RECORD	COMMENTS	OPERATOR
DA	MO	YR	START	STOP	CODE	CODE	ELEMENT	NUMBER	-NO	NO.		
28	01	74	1815	1825	UT	S				U-127	SE-S RERAN Successfully	<i>Mah</i>
28	01	74	1850	1944	UT	S				U-145		<i>Mah</i>
28	01	74	1915	1944	UT	S				U-142		<i>Mah</i>
28	01	74	1920	1945	UT	S				U-125		<i>Mah</i>
28	01	74	1945	1955	UT	S				U-123		<i>Mah</i>
28	01	74	1945	2010	UT	S				U-124		<i>Mah</i>
28	01	74	1950	2022	UT	S				U-139		<i>Mah</i>
28	01	74	2020	2050	UT	S				U-143		<i>Mah</i>
28	01	74	2020	2125	UT	S				U-137		<i>Mah</i>
28	01	74	2021	2126	UT	S				U-148		<i>Mah</i>
28	01	74	2032	2010	ST	S				S-122		<i>Mah</i>
28	01	74	2100	2115	UT	S				U-147		<i>Mah</i>
28	01	74	2128	2220	UT	S				U-136		<i>Mah</i>
28	01	74	2128	2225	UT	S				U-119		<i>Mah</i>
28	01	74	2128	2230	UT	S				U-118		<i>Mah</i>
28	01	74	2230	2240	UT	S				U-139		<i>Mah</i>
28	01	74	2250	0020	UT	S				U-146		<i>Mah</i>
28	01	74	2350	0001	UT	S				U-114		<i>Mah</i>
29	01	74	0001	0125	UT	S				U-133		<i>Mah</i>
29	01	74	0125	0150	ST	S				S-001		<i>Mah</i>
29	01	74	0150	0200	ST	OE				S-002		<i>Mah</i>
29	01	74	0200	0245	ST	DF	7201-02	50051	T-03	S-003		<i>Mah</i>
29	01	74	0250	0315	ST	S				S-002		<i>Mah</i>
29	01	74	0320	0325	ST	S				S-004		<i>Mah</i>

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION

MALFUNCTION RECORD							USAGE CODES			OPERATION CODES		APPROVAL <i>H. Hurst</i> DATE 31/1/74
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL		
							ST	SYSTEM TEST	DF	DETECTED FAILURE		
							FE	FACTORY EXERCISE	PF	PROGRAM FAILURE		
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE		
							SU	SETUP TIME	XF	EXTERNAL FAILURE		
							SM	SCHED MAINT	UF	UNDETECTED FAILURE		
							UM	UNCHED MAINT	OE	OPERATOR ERROR		
							FM	FACT EXER MARGINS				

# ACCEPTANCE TEST LOG

DATE		TIME		USAGE	OPER	FAILURE DATA			TEST RECORD	COMMENTS	OPERATOR	
DA	MO	YR	START	STOP	CODE	CODE	UNIT OR ELEMENT	SERIAL NUMBER	TYPE -NO			NO.
29	01	74	0325	0355	ST	S				S-003	Re-run successful	Mal
29	01	74	0400	0410	ST	S				S-006		Mal
29	01	74	0410	0420	ST	S				S-007		Mal
29	01	74	0420	0425	ST	S				S-124		Mal
29	01	74	0425	0430	SU							Mal
29	01	74	0430	0600	ST	S				S101		Mal
29	01	74	0600	0630	ST	DF	CE-1	50050	T04	S101	ROS Parity Error	Mal
29	01	74	0630	0816	ST	S				S-101	Re-runs for T-04 successful.	Mal
29	01	74	0816	0822	ST					S-101		R. J. Reilly
29	01	74	0822	0833	ST	S				S-101		R. J. Reilly
29	01	74	0833	0837	SU							R. J. Reilly
29	01	74	0837	0850	ST	DF	TD-933	36013	T05	S-101		R. J. Reilly
29	01	74	0850	0908	ST	DF	TD-221	36004	M-06	S-101		R. J. Reilly
29	01	74	0908	0925	ST	DF				S-101	Re-run unsuccessful for M-06	R. J. Reilly
29	01	74	0925	1157	ST	DF	DSU-950	17253	T-06	S-101	Data check on Disk drive 950.	R. J. Reilly
29	01	74	1157	1230	ST	S				S-101	Re-run for T-06 successful.	R. J. Reilly
29	01	74	1230	1235	SU					S-101		R. J. Reilly
29	01	74	1235	1246	ST	S				S-101		R. J. Reilly
29	01	74	1246	1250	SU					S-101		R. J. Reilly
29	01	74	1250	1302	ST	S				S-101		R. J. Reilly
29	01	74	1302	1307	SU					S-101		R. J. Reilly
29	01	74	1307	1518	ST	S				S-101		R. J. Reilly
29	01	74	1518	1524	SU					S-101	M-07 Re-runs successful	R. J. Reilly
29	01	74	1524	1540	ST	S				S-101	Pass 2E repeated 3 times at observer request.	R. J. Reilly

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION

MALFUNCTION RECORD						USAGE CODES			OPERATION CODES		
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL	
29	01	74	06	R. J. Reilly	Malins	29-01-74	ST	SYSTEM TEST	DF	DETECTED FAILURE	
							FE	FACTORY EXERCISE	PF	PROGRAM FAILURE	
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE	
							SU	SETUP TIME	XF	EXTERNAL FAILURE	
							SM	SCHED MAINT	UF	UNDETECTED FAILURE	
							UM	UNSCHED MAINT	OE	OPERATOR ERROR	
							FM	FACT EXER MARGINS			

APPROVAL G. Hunt

DATE 31/1/74

							FAILURE DATA			TEST RECORD NO.	COMMENTS	OPERATOR
DATE		TIME		USAGE CODE	OPER CODE	UNIT OR ELEMENT	SERIAL NUMBER	TYPE -NO				
DA	MO	YR	START	STOP	CODE	CODE	ELEMENT	NUMBER	-NO			
29	01	74	1540	1710	ST	S				S-101		Remy
29	01	74	1710	1713	SU					S-101	Exercised 2 passes of I/O	Remy
29	01	74	1713	1724	ST	S				S-101		Remy
29	01	74	1724	1732	SU					S-101		Remy
29	01	74	1732	1847	ST	DF	825109	57987	T-07	S-101		Remy
29	01	74	1847	1918	ST	S				S-101	Returns for T-07 successful	Remy
29	01	74	1918	1950	ST	DF	2312A1	17254	T-08	S-101		Remy
29	01	74	1950	2016	ST	S				S-101		Remy
29	01	74	2016	2018	ST	S				S-101		Mal
29	01	74	2018	2038	ST	S				S-101	Exercised 2 passes of I/O	Mal
29	01	74	2043	2050	ST	S				S-139		Mal
29	01	74	2050	2054	ST	S				S-140		Mal
29	01	74	2054	2058	ST	S				S-141		Mal
29	01	74	2058	2110	ST	DF	7289-02	87072	T-09	S-131		Mal
29	01	74	2110	2113	ST	S				S-131	Returns for T-09 successful	Mal
29	01	74	2120	2130	ST	S				S-132		Mal
29	01	74	2120	2200	ST	S				S-133		Mal
29	01	74	2200	2235	ST	S				S-134		Mal
29	01	74	2260	2320	ST	S				S-135		Mal
29	01	74	2300	2335	ST	S				S-136		Mal
29	01	74	2200	2335	ST	S				S-137		Mal
29	01	74	2200	2310	ST	S				S-138		Mal
29	01	74	2340	0000	ST	DF	7251-09	57986	M-07	S-160		Mal
29	01	74	0000	0020	ST	S				S-160	Successfully completed 2 passes of SEVA	Mal

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION

MALFUNCTION RECORD							USAGE CODES			OPERATION CODES	
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL	
29	01	74	407	Malin	Malin	290174	ST	SYSTEM TEST	DF	DETECTED FAILURE	
							FE	FACTORY EXERCISE	PF	PROGRAM FAILURE	
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE	
							SU	SETUP TIME	XF	EXTERNAL FAILURE	
							SM	SCHED MAINT	UF	UNDETECTED FAILURE	
							UM	UNSCHED MAINT	OE	OPERATOR ERROR	
							FM	FACT EXER MARGINS			

APPROVAL G. Hurst  
 DATE 31/1/74

22



DATE			TIME		USAGE	OPER	FAILURE DATA			TEST RECORD NO.	COMMENTS	OPERATOR
DA	MO	YR	START	STOP	CODE	CODE	UNIT OR ELEMENT	SERIAL NUMBER	TYPE -NO			
30	01	74	0020	2235	ID							Mal
30	01	74	2235	2250	UT	S				U-021	1052 S/N 30141, 42, 38, 45	Mal
30	01	74	2250	2315	UT	DF	1052-07	30141	M-08	U-139		Mal
30	01	74	2315	2325	UT	DF	1052-07	30138	M-09	U-139		Mal
30	01	74	2325	2335	UT	S				U-139	1052 S/N's 30142, 45	Mal
30	01	74	2335	2345	UT	S				U-139	1052 S/N's 30141	Mal
30	01	74	2345	0005	UT	DF	1052-07	30069	M-10	U-021	1052 S/N's 30125, 30139, 30069	Mal
31	01	74	0005	0025	UT	S	1052			U-139	1052 S/N's 30139, 30125	Mal
31	01	74	0025	0030	UT	S				U-139	1052 S/N's 30139, 30125	Mal
31	01	74	0030	0035	UT	S				U-021	1052 S/N's 30068, 30137	Mal
31	01	74	0035	0045	UT	S				U-139	1052 S/N's 30068, 30137	Mal
31	01	74	0045	0050	UT	S				U-139	1052 S/N 30130	Mal
31	01	74	0050	0100	UT	S				U-021	1052 S/N's 30144, 30146, 30143, 30140	Mal
31	01	74	0100	0120	UT	S				U-139	1052 S/N's 30144, 30146, 30143, 30140	Mal
31	01	74	0120	0300	ID							Mal
31	01	74	0300	0307	UT	S				U-021	1052 S/N 30069 Re-run Successful.	Mal
31	01	74	0307	0320	UT	S				U-139	1052 S/N's 30069, 30138 Re-run Successful	Mal
31	01	74	0320								Test Complete	Mal

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION

MALFUNCTION RECORD						USAGE CODES			OPERATION CODES		
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL	
30	01	74	08	Malin	Malin	30-01-74	ST	SYSTEM TEST	DF	DETECTED FAILURE	
30	01	74	09	Malin	Malin	31-01-74	FE	FACTORY EXERCISE	PF	PROGRAM FAILURE	
30	01	74	10	Malin	Malin	31-01-74	ID	IDLE IN ORDER	MF	MATERIAL FAILURE	
							SU	SETUP TIME	XF	EXTERNAL FAILURE	
							SM	SCHED MAINT	UF	UNDETECTED FAILURE	
							UM	UNSCHED MAINT	OE	OPERATOR ERROR	
							FM	FACT EXER MARGINS			

APPROVAL G. Hurst  
 DATE 31/1/74

23

**IBM 9020D/E SYSTEM**

**UNIT FUNCTIONAL TEST DATA RECORD**

TEST NO.	ELEMENT/UNIT
1	CE#1
2	CE#2
3	CE#3
4	CE#4

TEST DATA RECORD NO. U- 001  
 LOCATION UNITED KINGDOM  
 DATE 28-01-74  
 TEST SPEC. REF. 5.1.1

TEST CONFIGURATION	CE				IOCE			SE					SE/DE					DAU		PAM			SCU			TCU			SC/CC	RCU		
	1	2	3	4	1	2	3	1	2	3	4	5	6	7	8	9	10	1	2	1	2	3	1	2	3	1	2	3	1	1	2	
	1	X																														
	2		X																													
	3			X																												
4																																

PROGRAM AND SECTION ID	TEST RESULT	CERTIFICATION
Switch Demonstration CE#1	Success	<i>W/h</i>
Switch Demonstration CE#2	Success	<i>W/h</i>
Switch Demonstration CE#3	Success	<i>W/h</i>
Switch Demonstration CE#4	N/A	

TEST NO.	MALFUNCTION NO.	RERUN REQ'D	TEST NO.	MALFUNCTION NO.	RERUN REQ'D.
1			3		
2			4		

COMMENTS

APPROVAL *G. Hurst*  
 DATE 28/1/74

Contract FA64WA-5223

IBM 9020D/E DATA PROCESSING SYSTEM  
FOR  
UNITED KINGDOM 9020D TRIPLEX SYSTEM  
FACTORY ACCEPTANCE TEST REPORT  
FOR ITEMS TESTED AS PER AMENDMENT #88  
October 2, 1973 thru October 9, 1973

This information is furnished in accordance with requirements of Contract No. FA64WA-5223 and is subject to Clause 24 thereof entitled, "Reproduction and Use of Technical Data" which provides for its use, reproduction or disclosure by the Government for Government purposes.

INTERNATIONAL BUSINESS MACHINES CORPORATION

## CONTENTS

CONTENTS	ii
INTRODUCTION	1
ACCEPTANCE TEST SUMMARY	1
QUALITY CONTROL COMMENTS	4
EC/REA STATUS	4
EQUIPMENT IDENTIFICATION LIST	5
SPECIAL FEATURES AND RPQ LIST	8
SEVA EXERCISE GRAPH	11
TEST FLOOR DIAGRAM	17
9020D/E ACCEPTANCE TEST LOGS AND RECORDS	18

## Introduction

The Factory Acceptance Test for the United Kingdom Triplex 9020D System was conducted from October 2, 1973 through October 9, 1973. The test was run in accordance with the concurred upon Test Check List entitled, "IBM 9020D/E System Acceptance Test Check List" and "IBM 9020D/E Data Processing System Factory and Field Acceptance Test Specification - Revision 7."

Because of a unique problem with Printer/Keyboard S/N 30136 (Position #3), it was removed from the System configuration and returned to the Raleigh Plant. A replacement Printer/Keyboard will be tested in the #3 position and the results shown in a separate test report.

All other tests that were scheduled to be performed as a part of the Acceptance Test were completed successfully.

The errors encountered during this test are placed into the following categories:

1. Transient Failure - an error which does not recur upon repeated runs of the same routine.
2. Malfunction - an error which recurs upon repeated runs of the same routine or, in the case of the SEVA exercise, the same error occurring on successive passes of the program.

During the Factory Acceptance Test, a total of seventeen (17) transients and fourteen (14) malfunctions occurred.

NOTE 1. Two REAs (06-66548 and 06-66549) were installed on IOCE3 resulting from several related transients identified in the Acceptance Test Summary. The REAs corrected the identified problems and reruns of SEVA were performed to the satisfaction of IBM and the FAA Kingston plant representative.

## Acceptance Test Summary

The Factory Acceptance Test consisted of Element Manual Tests, Element, Subsystem and System Functional Tests, and the Factory Exercise (SEVA).

During the Element Manual Tests three malfunctions occurred. These are described below.

M-01 Test U-003 SE3 S/N 51988 encountered Key Checks, Dropping Bit 21 in Storage Protect. Corrective action was the replacement of card P/N 5804631 at location 03CA4G2.

Reruns were completed successfully on SE 3.

- M-02 Test U-018 SCU 1 S/N 19271 encountered an E-9 error during in-line Microdiagnostics. The B-Y Register was failing to increment. Corrective action was the replacement of Card P/N 5800015 at Location AA3B5. Reruns were completed successfully on SCU 1.
- M-03 Test U-019 Tape Drive 2-1 S/N 36001 would not sense Load Point. Corrective action required increasing the voltage on the Load Point Sense Lamp. Reruns were completed successfully on TD 2-1.

During the Element/Subsystem Functional Tests, one Transient and three Malfunctions occurred. These are described below.

- M-04 Test U-127 SE 4 S/N 51989 encountered Storage Checks while acting as the Resident SE for Monitor. Corrective action required replacing the LO/ODD BSM. Reruns were completed successfully with SE 4.
- M-05 Test U-127 SE 6 S/N 51991 failed to Log Out Data Error while executing Diagnostic D22A4. Corrective action required replacing an Inverter Card at Location 03C2H5. Reruns were completed successfully.
- T-01 Test U-135 PAM 3 S/N 89074 encountered a Data Byte Check at Address 31.
- M-06 Test U-139 Printer/Keyboard 3 S/N 30136 printed erroneous characters during the Diagnostic tests. Corrective action required making numerous adjustments to the Printer/Keyboard. Reruns were completed successfully.

During the System Functional tests, three malfunctions occurred. These are described below.

- M-07 Test S-002 SCU 1 S/N 19271 Diagnostic D6A2 developed unknown interrupts. Bit 3/Byte 4 of sense information was intermittently not setting. Corrective action required replacing the card at Location A A1J2. Reruns were completed successfully on SCU 1.
- M-08 Test S-134 IOCE 2 S/N 11085 does not indicate on Battery or go On Battery. Corrective action required reseating the Battery Recharge Relay Card. Reruns were completed successfully.

M-09 Test S-134 A faulty switch was found on the Main Line circuit breaker on SE 5 S/N 51990. Corrective action required replacing the Circuit Breaker on SE 5. Reruns were completed successfully.

During the Factory SEVA Exercise, sixteen transients and five malfunctions occurred. These problems are described below in the order that they occurred.

- T-02 PAM 2 indicated "GPO Busy"
- M-10 Tape Drive 2-1 S/N 36001 failed a Read Backward operation. Corrective action required replacing a card in Location 01A1D10. Reruns were successful.
- T-03 SE 3 S/N 51988 SDBI Check CE 3 to SE 3.
- M-11 SE 1 S/N 51986 SEVA pass A9 failed IOCE processor program, with Storage Bus In Errors. (IOCE 3 to SE 1). Corrective Action: Straighten Pin in Termination Socket at Location 02S-B3A1 (Bit 5 was unterminated) Reruns were successful.
- T-04<sup>1</sup> IOCE 3 S/N 11086 I/O Processor Program E3B5 failed indicating MACH data area not clear to zeroes.
- T-05 TCU 2 S/N 12228 caused a Program Interrupt - F20 Hang.
- M-12 CE 3 S/N 50052 encountered SDBI and Local Store Parity Checks. Corrective action required reseating a card at Location AA4E5. Reruns were successful.
- T-06<sup>1</sup> IOCE 3 S/N 11086 encountered a Program Interrupt - MACH Data area not cleared to zeroes.
- T-07<sup>1</sup> IOCE 3 S/N 11086 encountered a Program Interrupt - MACH Data area not clear to zeroes. (Section E3B5).
- T-08<sup>1</sup> IOCE 3 S/N 11086 encountered a Section E3B5 failure - MACH Data area not cleared to zeroes.
- T-09 CE 1 S/N 50050 encountered a Compare Error during a Convert Weather Line instruction.
- T-10<sup>1</sup> IOCE 3 S/N 11086 encountered a Program Interrupt - Section E3B5.
- T-11 SE 7 S/N 51992 encountered a Storage Data Bus Out Check (CE2/SE7)
- M-13 Tape Drive 3-1 S/N 36000 encountered a Compare Error. Corrective action required replacing an FHA card at Location 01AD8. Reruns were successful.

- M-14 SE 7 S/N 51992 encountered a Storage Data Bus Out Check. Corrective action required replacing the array for the Lo: Even BSM. Reruns were successful.
- T-12 CE 2 S/N 50051 encountered a Machine Check Interrupt at SEVA Pass B7.
- T-13<sup>1</sup> IOCE 3 S/N 11086 encountered a Section E3B5 error. MACH area not cleared to zeroes.
- T-14<sup>1</sup> IOCE 3, S/N 11086 encountered a Section E3B5 Program Interrupt.
- T-15<sup>1</sup> IOCE 3 S/N 11086 encountered a Section E3B5 MACH Area not cleared to zeroes error.
- T-16 CE2 S/N 50051 encountered an Invalid Logout at Pass Count 34 (Parallel Adder Full Sum Check 64-67 with other errors).
- T-17 CE3 S/N 50052 encountered a Parallel Adder Full Sum Check 32-39/40-47.

#### Quality Control Comments

It was decided by FAA and IBM that the Certified Quality Analysis Factory Inspection performed prior to shipment would fulfill the Acceptance Test Quality Control requirements as outlined in the IBM 9020D/E System Acceptance Test Check List, Section 2.1

#### EC/REA Status

The following EC and REAs were installed on the System prior to shipment to the United Kingdom.

EC 739453 - installed on all 7289-02 PAMs (Teletype End of Message modification)

REA 06-66548 - installed on all 7231-02 IOCEs to prevent possibility of intermittent improper reset of "Proceed on Interrupt" latch.

REA 06-66549 - installed on all 7231-02 IOCEs to prevent possibility of intermittent improper Condition Code setting.



# IBM EQUIPMENT IDENTIFICATION LIST

Location United Kingdom 9020D Triplex (Factory)

Date OCT 9 1973

EQUIPMENT NAME	MODEL NO.	POSITION/ ADDRESS	SERIAL NO.
Compute Element	7201-02	1	50050
		2	50051
		3	50052
Input/Output Control Element	7231-02	1	11084
		2	11085
		3	11086
Storage Element	7251-09	1	51986
		2	51987
		3	51988
		4	51989
		5	51990
		6	51991
		7	51992
System Console	7265-02	1	65025
Tape Control Unit	2803-01	1	12227
		2	12228
		3	12229
Tape Drives	2401-03	10	36005
		11	36006
		<del>20</del> 21	36001 ✓
		<del>21</del> 20	36004
		<del>30</del> 31	36000 ✓
		<del>31</del> 30	36012
Peripheral Adapter Modules Adapters:	7289-02	1	89072
		20	CD
		7	TTY
		6	FDEP
		3	GPI
		26	GPO
		7	1052
		5	INTI
		5	INTO

1  
2  
3  
4  
5  
6

CONTRACT #FA64WA-5223

AMENDMENT	ITEM	AMENDMENT	ITEM
147	213, 213.1		

Approval *[Signature]*

Date OCT 9 1973

# IBM EQUIPMENT IDENTIFICATION LIST

Location United Kingdom 9020D Triplex (Factory) Date OCT 9 1973

EQUIPMENT NAME	MODEL NO.	POSITION/ ADDRESS	SERIAL NO.
Peripheral Adapter Modules Adapters: 20 CD 6 TTY 5 FDEP 2 GPI 27 GPO 7 1052 5 INTI (B) 5 INTO (B)	7289-02	2	89073 ✓
Peripheral Adapter Modules Adapters: 20 CD 7 TTY 5 FDEP 3 GPI 27 GPO 7 1052 4 INTI (B) 4 INTO (B)	7289-02	3	89074 ✓
Storage Control Unit	2314-A1	1 2 3	19271 ✓ 19272 ✓ 19273 ✓
Disk Storage Unit	2312-A1	1-1 2-1 3-1	17253 ✓ 17254 ✓ 17255 ✓
Reader/Punch	2540-01		23054 —
Printer	1403-02	1 2	21332 — 21333 —
Integrated Control Unit	2821-01 2821-02	1 2	18869 ✓ 24095 ✓

CONTRACT #FA64WA-5223			
AMENDMENT	ITEM	AMENDMENT	ITEM
147	213, 213.1		

Approval *[Signature]* Date OCT 9 1973  
6

# IBM EQUIPMENT IDENTIFICATION LIST

Location United Kingdom 9020D Triplex (FACtory)

Date OCT 9 1973

EQUIPMENT NAME	MODEL NO.	POSITION/ ADDRESS	SERIAL NO.
Printer/Keyboard	1052-07	1 2 * 3	30128 ✓ 30135 ✓ 30136 ✓
<p>* Removed from System due to unsatisfactory performance. Position #3 will be replaced with another 1052-07.</p>			

CONTRACT #FA64WA-5223			
AMENDMENT	ITEM	AMENDMENT	ITEM
147	213, 213.1		

Approval [Signature]

Date OCT 9 1973

## IBM 9020D/E DATA PROCESSING SYSTEM

## SPECIAL FEATURES AND RPQ's INSTALLED ON THE UNITED KINGDOM 9020D TRIPLEX

The following features and/or RPQ's are installed on each of the units listed below:

Compute Element 7201-02

RPQ FA0416      CCR/DAR Modification for 2314A1  
Connection to 9020D

RPQ F30767      Wrap Bus Modification

RPQ FB0140      Convert and Sort Symbols/Convert  
Weather Lines

Input/Output Control Element 7231-02

RPQ F16374      Address Translation

RPQ F27112      Expanded Addressing

RPQ F21241      Processor Mode

RPQ F20974      Storage Element (64K) Interface  
Mod.

~~RPQ F27111      Power Mod.~~ *[Handwritten signature]*

~~RPQ F16375      SE Bus Mod.~~ *[Handwritten signature]*

System Console 7265-02

RPQ F16378      Single Enter-Cancel Keys

RPQ F16379      Patch Panel and Adapter Unit

RPQ F20421      SMMC Interface Mod.

RPQ F16373      Fourth CE Modification

RPQ FA0417      Configuration and State Display  
Modification for 2314A1 Connection  
to 9020D

Peripheral Adapter Module 7289-02

RPQ F26474      Power Mod.

RPQ F19673      Two Level Shared Priority

RPQ FA1771      Power Mod. 1052

## SPECIAL FEATURES AND RPQ'S INSTALLED ON THE UNITED KINGDOM 9020D TRIPLEX

(cont'd)

Tape Unit Control 2803-A01

RPQ F12928 Switching to IOCE's

Direct Access Storage Facility 2314-A01RPQ FA0418 Configuration Control Modification  
to 2314A1 for connection to 9020A  
and 9020D

Feature 8170 Two Channel Switch

Integrated Control Unit 2821-01

Feature 8637 Universal Character Set Adapter

Feature 9241 1403-02 Attachment 01 and 02

Integrated Control Unit 2821-02

Feature 8637 Universal Character Set Adapter

Feature 8100 Two Channel Switch

Feature 9241 1403-02 Attachment 01 and 02

Printer/Keyboard 1052-07

Feature 9572 Extended BCD Code Print Element

Feature 9104 10 Characters/Inch Horizontal Spacing

Feature 9509 Pin Feed Platen

Feature 9162 Line Spacing 6 LPI, 13-1/8"  
Hole-to-Hole Width

RPQ F13197 Cable and Power on Indicator

RPQ F14713 Single Enter and Cancel Keys

Feature 9903 208v 60 Hz

Printer 1403-02


Feature 8641 Universal Character Set

SPECIAL FEATURES AND RPQ's INSTALLED ON THE UNITED KINGDOM 9020D TRIPLEX











(cont'd)

Feature 4740 Interchangeable Chain Cartridge  
Adapter

Feature 9631 PN-2 Print Arrangement

Approval: 

Date: OCT 9 1973



Exercise Interrupt

Active System

Redundant System

M - Malfunction


Scheduled Maintenance

T - Transient


Unscheduled Maintenance

Factory Margins














11



12

EXERCISE INTERRUPT  **A** Active System      **R** Redundant System      **SM** Scheduled Maintenance      **UM** Unscheduled Maintenance      **M** Factory Margins  
**M** - Malfunction      **T** - Transient






EXERCISE INTERRUPT

**A** Active System      **R** Redundant System      **SM** Scheduled Maintenance      **UM** Unscheduled Maintenance      **M** Factory Margins

**M** - Malfunction      **T** - Transient

13



14

EXERCISE INTERRUPT

- A Active System
- R Redundant System
- SMI Scheduled Maintenance
- UMI Unscheduled Maintenance
- M Factory Margins
- M - Malfunction
- T - Transient

100 104 108 112 116 120 124  
123

CE 1 R A

CE 2 M A R  
T-16

CE 3 R A  
T-17

IOCE 1 R A

IOCE 2 M A

IOCE 3 R A R  
T-13, T-14 T-15

SE 1 R A

15

SE 2 M A

SE 3 M A R

SE 4 M A R A

SE 5 R A

SE 6 A R

SE 7 A

A Active System

R Redundant System

SM Scheduled Maintenance


UM Unscheduled Maintenance

M Factory Margins

M - Malfunction


T - Transient

100 104 108 112 116 120 123 124



16

A Active System     
 R Redundant System     
 SM Scheduled Maintenance     
 UM Unscheduled Maintenance     
 M Factory Margins  
 M - Malfunction      T - Transient



UNITED KINGDOM TRIPLEX 9020 D  
 FACTORY FLOOR DIAGRAM  
 OCTOBER 2, 1973

DATE				TIME		USAGE CODE	OPER CODE	FAILURE DATA			TEST RECORD NO.	COMMENTS	OPERATOR	
DA	MO	YR	START	STOP	UNIT OR ELEMENT			SERIAL NUMBER	TYPE -NO					
02	10	73	0845	1130	UT	S					U-001		W. Smith	
02	10	73	0845	1025	UT	S					U-002		W. Smith	
02	10	73	0845	1200	UT	S					U-003, U-004, U-006, U-007		W. Smith	
02	10	73	0845	0915	UT	S					U-017		W. Smith	
02	10	73	0916	1300	UT	S					U-018		W. Smith	
02	10	73	0845	0930		DF	7258-04	51988	M-01			SEA 3 KEY CHECK TEST U-003		W. Smith
02	10	73	0930	1000	UM							WORKING ON SEA 3		W. Smith
02	10	73	0845	0915		DF	2314 A1	19271	M-02			SCU #1 E-9 ERROR		W. Smith
02	10	73	0915	1300	UM							WORKING ON SCU #1		W. Smith
02	10	73	1025	1040	UT	S					U-013		W. Smith	
02	10	73	1041	1125	UT	S					U-014		W. Smith	
02	10	73	1100	1210	UT	S					U-019		W. Smith	
02	10	73	1145	1200	UT	S					U-020		W. Smith	
02	10	73	1146	1205	UT	S					U-021		W. Smith	
02	10	73	1100	1120		DF	2401-03	36001	M-03		U-019	TD 2-1 DOES NOT SENSE LOAD POINT		W. Smith
02	10	73	1215	1525	ST	S						RAM TWO LEVEL SHARED PRIORITY		W. Smith
			-	-								DEMONSTRATION AMEND #8 ATTRIBUTES #1		W. Smith
02	10	73	1300	1410	UT	S					U-101	CE1 DIAGS.		W. Smith
02	10	73	1411	1440	UT	S					U-102	CE2 DIAGS.		W. Smith
02	10	73	1441	1500	UT	S					U-103	CE3 DIAGS.		W. Smith
02	10	73	1501	1525	UT	S					U-105	ATR TEST		W. Smith
02	10	73	1530	1536	UT	S					U-106			W. Smith
02	10	73	1537	1545	UT	S					U-107			W. Smith
02	10	73	1546	1555	UT	S					U-108			W. Smith
02	10	73	1245	1300	UT	S					U-018	REPAIR DISE-1 (M-02)		W. Smith

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION

MALFUNCTION RECORD						USAGE CODES			OPERATION CODES		
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL	
02	10	73	01	W. Smith	W. Smith	10/2/73	ST	SYSTEM TEST	DF	DETECTED FAILURE	
02	10	73	02	W. Smith	W. Smith	10/2/73	FE	FACTORY EXERCISE	PF	PROGRAM FAILURE	
02	10	73	03	W. Smith	W. Smith	10/2/73	ID	IDLE IN ORDER	MF	MATERIAL FAILURE	
							SU	SETUP TIME	XF	EXTERNAL FAILURE	
							SM	SCHED MAINT	UF	UNDETECTED FAILURE	
							UM	UNSCHED MAINT	OE	OPERATOR ERROR	
							FM	FACT EXER MARGINS			

APPROVAL *W. Smith*  
 DATE 10/9/73

18

U K FACTORY

ACCEPTANCE TEST LOG #2

DATE				TIME		USAGE CODE	OPER CODE	FAILURE DATA			TEST RECORD NO.	COMMENTS	OPERATOR
DA	MO	YR	START	STOP	UNIT OR ELEMENT			SERIAL NUMBER	TYPE -NO				
02	10	73	1600	1705	UT	S					U-126		W. J. Stankard
02	10	73	1600	1730	UT	S					U-127		W. J. Stankard
02	10	73	1600	1640	UT	S					U-128		W. J. Stankard
02	10	73	1600	1615		DF	7251-09	51989	11-04		SE#4 (U-127) STORAGE CHECK		W. J. Stankard
02	10	73	1615	1745	UM						WORK ON SE 4 (M-04)		W. J. Stankard
02	10	73	1600	1700		DF	7251-09	51991	11-05		SE#6 DATA ERROR LOG-OUT FAILURE		W. J. Stankard
02	10	73	1700	1740	UM						WORK ON SE6 (M-05)		W. J. Stankard
02	10	73	1710	1720	UT	S					U-109	DASF 1	W. J. Stankard
02	10	73	1715	1740	UT	S					U-127	RE RUN SUCCESSFUL ON SE6 (M-05)	W. J. Stankard
02	10	73	1720	1740	UT	S					U-110	DASF 2	W. J. Stankard
02	10	73	1740	1755	UT	S					U-111	DASF 3	W. J. Stankard
02	10	73	1800	1825	UT	S					U-112	TCU 1	W. J. Stankard
02	10	73	1800	1845	UT	S					U-127	RE RUN SE#4 (M-04)	W. J. Stankard
02	10	73	1826	1840	UT	S					U-114	TCU 2	W. J. Stankard
02	10	73	1840	1900	UT	S					U-116	TCU 3	W. J. Stankard
02	10	73	1900	1910	UT	S					U-118	DASF TCS	W. J. Stankard
02	10	73	1910	1920	UT	S					U-119	TCU DUAL INFE	W. J. Stankard
02	10	73	1921	1930	UT	S					U-123	LOC 1	W. J. Stankard
02	10	73	1931	1945	UT	S					U-124	LOC 2	W. J. Stankard
02	10	73	1946	2000	UT	S					U-125	LOC 3	W. J. Stankard
02	10	73	2000	2053	UT	S					U-133	CE 1, CE 2, CE 3	W. J. Stankard
02	10	73	2015	2200	UT	DF	7289-02	89074	T-01		U-135	PAM DIAGS. PAM 3 Address 31 DATA BYTE CK	W. J. Stankard
02	10	73	2200	2208	UT	S					U-137		W. J. Stankard
02	10	73	2208	2300	UT	S					U-135	RE RUNS SUCCESSFUL TEST COMPLETE	W. J. Stankard

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION

MALFUNCTION RECORD						USAGE CODES			OPERATION CODES			APPROVAL	DATE
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL			
02	10	73	04	W. J. Stankard	W. J. Stankard	10/2/73	ST	SYSTEM TEST	DF	DETECTED FAILURE			
02	10	73	05	W. J. Stankard	W. J. Stankard	10/2/73	FE	FACTORY EXERCISE	PF	PROGRAM FAILURE			
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE			
							SU	SETUP TIME	XF	EXTERNAL FAILURE			
							SM	SCHED MAINT	UF	UNDETECTED FAILURE			
							UM	UNSCHED MAINT	OE	OPERATOR ERROR			
							FM	FACT EXER MARGINS					

APPROVAL: *[Signature]*  
 DATE: 10/9/73

U.K. FACTORY

# ACCEPTANCE TEST LOG #3

## FAILURE DATA

DATE	TIME	USAGE	OPER	UNIT OR	SERIAL	TYPE	TEST RECORD	COMMENTS	OPERATOR
DA MO YR	START STOP	CODE	CODE	ELEMENT	NO.	NO.	NO.		
02 10 73	2205 2215	UT	S				U-138		Urbank
02 10 73	2215 0045	UT	S				U-139		Urbank
02 10 73	2215 2240		DF	1052-07	30136	11-06		PRINTING WRONG CHARACTERS	Urbank
02 10 73	2240 <sup>03/1800</sup>	UM						WORK ON 1052 #3 (M-06)	Urbank
02 10 73	2220 2250	UT	S				U-142	10CE 1	Urbank
02 10 73	2220 2235	UT	S				U-143	10CE 2	Urbank
02 10 73	2235 0045	UT	S				U-145	10CE 1, 2, 3	Urbank
03 10 73	0045 0107	UT	S				U-136		Urbank
03 10 73	0110 0147	UT	S				U-146		Urbank
03 10 73	0111 0125	UT	S				U-144		Urbank
03 10 73	0125 0200	UT	S				U-147		Urbank
03 10 73	0200 0230	UT	S				U-148		Urbank
03 10 73	0231 0300	ST	S				S-120		Urbank
03 10 73	0300 0330	ST	S				S-123		Urbank
03 10 73	0331 0410	ST	S				S-001		Urbank
03 10 73	0410 0510	ST	S				S-002		Urbank
03 10 73	0410 0425		DF	2314 A1	14271	11-07		INDIRECT SENSE INFO FROM SCU#1	Urbank
03 10 73	0425 1445	UM						WORK ON SCU#1 (01-07)	Urbank
03 10 73	0511 0630	ID						MAINT SUBSYSTEMS BEING USED FOR 1052 #3 AND SCU#1 PROBLEMS.	Urbank
03 10 73	0640 1530	ST	S				S-135	COMPLETED AS EQUIP. BECAME AVAILABLE	Urbank
03 10 73	0645 1530	ST	S				S-136	COMPLETED AS EQUIP. BECAME AVAILABLE	Urbank
03 10 73	0645 1530	ST	S				S-137	COMPLETED AS EQUIP. BECAME AVAILABLE	Urbank
03 10 73	0645 1530	ST	S				S-138	COMPLETED AS EQUIP. BECAME AVAILABLE	Urbank

20

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION										
MALFUNCTION RECORD					USAGE CODES			OPERATION CODES		
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL
02	10	73	06	Urbank	Urbank	10/3/73	ST	SYSTEM TEST	DF	DETECTED FAILURE
03	10	73	07	Urbank	Urbank	10/3/73	FE	FACTORY EXERCISE	PF	PROGRAM FAILURE
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE
							SU	SETUP TIME	XF	EXTERNAL FAILURE
							SM	SCHED. MAINT.	OE	OPERATOR ERROR
							UM	UNSCHED. MAINT.		
							FM	FACT. EXER. MARG.		

APPROVAL *[Signature]*  
 DATE 10/9/79



UK FACTORY

# ACCEPTANCE TEST LOG #4

				FAILURE DATA			TEST RECORD NO.	COMMENTS	OPERATOR		
DATE	TIME	USAGE	OPER	UNIT OR	SERIAL	TYPE					
DA	MO	YR	START	STOP	CODE	CODE	ELEMENT	NO.	NO.		
03	10	73	1430	1445	ST	S			S-002	REWIN ON SCU#1 (M-07)	W. Smith
03	10	73	1446	1515	ID						W. Smith
03	10	73	1516	1530	ST	S			S-004		W. Smith
03	10	73	1535	1550	ST	S			S-003		W. Smith
03	10	73	1555	1625	ST	S			S-006		W. Smith
03	10	73	1630	1745	ST	S			S-007		W. Smith
03	10	73	1750	1800	ST	S			S-124		W. Smith
03	10	73	1801	1820	ST	S			S-131		W. Smith
03	10	73	1821	1900	ST	S			S-132		W. Smith
03	10	73	1821	1900	ST	S			S-133		W. Smith
03	10	73	1900	1915	UT	S			U-139	REWIN ON 1052#3 SUCCESSFUL (M-06)	W. Smith
03	10	73	1916	2110	ST	S			S-134		W. Smith
03	10	73	1916	1930		DF	7231-02	11085	M-08	IOCE#2 DOES NOT INDICATE OR GO CU BATTERY	W. Smith
03	10	73	1930	1935	UM					RESEATED BATTERY RECHARGE RELAY (CAL)	W. Smith
03	10	73	1935	1940	ST	S			S-134	REWIN OK ON IOCE#2 (M-08)	W. Smith
03	10	73	1916	1940		DF	7251-09	57990	M-09	SE#5 BAD MAIN LINE CB (CB1)	W. Smith
03	10	73	1940	0400	UM					WORK ON BAD CB - NEEDS NEW CB, CRACKED AND REWAVE	W. Smith
03	10	73	2115	2229	ID					PRE SEVA CLEANUP	W. Smith
03	10	73	2230	2345	FM	S			S-150	SEVA, 2 PASSES I/O, -BIAS	W. Smith
03	10	73	2230	0345		DF	7289-02	88073	F-02	PM#2 INDICATES EPO BUSY	W. Smith
03	10	73	0345	0630	FM	S			S-150	APPLIED +BIAS AT 0430 (REWIN FOR OK)	W. Smith
03	10	73	0630	0640	SU					RECONFIGURE SEVA	W. Smith

21  
03

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION										
MALFUNCTION RECORD					USAGE CODES			OPERATION CODES		
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL
03	10	73	08	W. Smith	W. Smith	10/3/73	ST	SYSTEM TEST	DF	DETECTED FAILURE
03	10	73	09	W. Smith	W. Smith	10/4/73	FE	FACTORY EXERCISE	PF	PROGRAM FAILURE
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE
							SU	SETUP TIME	XF	EXTERNAL FAILURE
							SM	SCHED. MAINT.	OE	OPERATOR ERROR
							UM	UNSCHED. MAINT.		
							FM	FACT. EXER. MARG.		

APPROVAL *W. Smith*  
DATE 10/9/73

UK FACTORY

# ACCEPTANCE TEST LOG #5

				FAILURE DATA			TEST RECORD NO.	COMMENTS	OPERATOR		
DATE	TIME	USAGE	OPER	UNIT OR	SERIAL	TYPE					
DA	MO	YR	START	STOP	CODE	CODE	ELEMENT	NO.	NO.		
04	10	73	0640	0840	FM	S			S-150	SEVA RECONFIGURED, +BIAS,	Wibbly
04	10	73	0640	0840		DF	2401-03	36001	M-10	TD 2-1 FAILS READ BACKWARD	Wibbly
04	10	73	0840	0900	UM					REMOVED TCU#2 TO WORK ON	Wibbly
										TD 2-1 - ADDED TCU#1 INTO SYSTEM	Wibbly
04	10	73	0840	1015	FM	S			S-150	RESUME SEVA AT +BIAS WITH	Wibbly
										TCU 1 AND TCU 3	Wibbly
04	10	73	1015	1575	FM	S			S-150	RECONFIGURED TCU 2 / TD 2-1	Wibbly
										BACK INTO SYSTEM, REMOVED +	Wibbly
										BIAS FROM SYSTEM.	Wibbly
04	10	73	1515	1524	SU					RECONFIGURE SEVA	Wibbly
04	10	73	1524	1700	FE	S			S-150	RESUME SEVA, 2 PASSES I/O	Wibbly
04	10	73	1015	1420		DF	7251-09	51988	T-03	CE3/SE3 SDB1 CHECK / REPAIRS OK	Wibbly
04	10	73	1524	1700		DF	7251-09	51986	M-11	SDB1 CHKS. 10CF3 TO SE1	Wibbly
04	10	73	1700	1735		DF	7251-09	51986	M-11	5TH RUN FAILS (M-11) PASS A9	Wibbly
04	10	73	1735	1930	FE	S			S-150	RECONFIGURE SEVA WITH REMOVED	Wibbly
										ELEMENT TO ENABLE MAINT.	Wibbly
										ON 10CF3 / SE1	Wibbly
04	10	73	1930	2230	FE	S			S-150	CONFIGURED FOR 3HR MAINT.	Wibbly
										MODE	Wibbly
04	10	73	2230	2239	SU					RECONFIGURE SEVA	Wibbly
04	10	73	2240	0630	FE	S			S-150	RESUME SEVA IN A-1 MODE	Wibbly
04	10	73	2240	-						REPAIR CONTACTS ON SE1 (M-11)	Wibbly
04	10	73	022230	0230		DF	723102	11086	T-04	TOP PGM. E3B5 (MACH WAS NOT	Wibbly
			-	-						CLEAR TO ZEROES)	Wibbly

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION

MALFUNCTION RECORD				USAGE CODES		OPERATION CODES		APPROVAL	DATE	
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT			UNIT TEST
04	10	73	10	Wibbly	Wibbly	10/4/73	ST	SYSTEM TEST	DF	DETECTED FAILURE
04	10	73	11	Wibbly	Wibbly	10/4/73	FE	FACTORY EXERCISE	PF	PROGRAM FAILURE
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE
							SU	SETUP TIME	XF	EXTERNAL FAILURE
							SM	SCHED. MAINT.	OE	OPERATOR ERROR
							UM	UNSCHED. MAINT.		
							FM	FACT. EXER. MARG.		

APPROVAL

DATE

*[Signature]*  
10/9/73

22

# UK FACTORY ACCEPTANCE TEST LOG #6

FAILURE DATA										TEST RECORD NO.	COMMENTS	OPERATOR
DATE	TIME		USAGE	OPER	UNIT OR	SERIAL	TYPE					
DA	MO	YR	START	STOP	CODE	CODE	ELEMENT	NO.	NO.			
05	10	73	0630	0640	SU						RECONFIGURE SEVA	Wick
05	10	73	0640	0950	FE	S				S-150	RESUME SEVA 2 PASSES I/O	Wick
05	10	73	0640	0651		MF					RENT CARD IN READER - CARD JAM	Wick
05	10	73	0640	0750		DF	2803A1	12228	T-05		PROGRAM INTERRUPT - FE/HANG FOUR	Wick
05	10	73	0730	0830	FE	S				S-150	5 RUNS OF PASS 0A OK (T-05)	Wick
05	10	73	0640	0950		DF	7201-02	50052	M-12		SDBCHK, LS. PTYCHK. CE 3	Wick
05	10	73	0950	1025		DF	7201-02	50052	M-12		RECONS FAILED WITH CE 3 (M-12)	Wick
05	10	73	1025	1330	SU						RECONFIGURE WITH REDUNDANT ELEMENT	Wick
05	10	73	1030	1455	FE	S				S-150	RESUME SEVA	Wick
05	10	73	1031	0255	UM						WORK ON CE 3 (M-12)	Wick
05	10	73	1030	1325		DF	7231-02	11086	T-06		REM INTERRUPT <sup>10</sup> MACH AREA NOT	Wick
											CLEARED TO ZEROES 5 RUNS OK.	Wick
05	10	73	1030	1335		DF	7231-02	11086	T-07		E3B5 REM INTERRUPT <sup>10</sup> MACH AREA	Wick
											NOT CLEARED TO ZEROES 5 RUNS OK	Wick
05	10	73	0255	0310	SU						RECONFIGURE SEVA	Wick
05	10	73	0310	2255	FE	S				S-150	RESUME SEVA	Wick
05	10	73	0350	1620		MF					TAPE SHATTERED ON DRIVE 3-1	Wick
05	10	73	2255	2305	SU							Wick
05	10	73	2305	0055	FE	S				S-150	5 RUNS OF PASS 16 FOR M-12 ALSO 2 PASSES OF I/O	Wick
05	10	73	2305	2315		MF					PAPER JAM IN 1403 #2	Wick
05	10	73	2305	045		DF	7231-02	11086	T-08		E3B5 MACH DATA AREA NOT CLEARED TO CE	Wick
05	10	73	2305	0330		DF	7201-02	50050	T-09		COMPARE ERROR ON CURRENT WEATHERLINE	Wick
05	10	73	0655	0705		SU					RECONFIGURE SEVA	Wick
05	10	73	0705	0900	FE	S					RESUME SEVA	Wick

FAILURE TYPE: T - TRANSIENT M - MALFUNCTION

MALFUNCTION RECORD						USAGE CODES			OPERATION CODES		
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL	
05	10	73	12	Wick	Wick	10/6/73	ST	SYSTEM TEST	DF	DETECTED FAILURE	
							FE	FACTORY EXERCISE	PF	PROGRAM FAILURE	
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE	
							SU	SETUP TIME	XF	EXTERNAL FAILURE	
							SM	SCHED. MAINT.	OE	OPERATOR ERROR	
							UM	UNSCHED. MAINT.			
							FM	FACT. EXER. MARG.			

APPROVAL: [Signature]

DATE: 10/9/73

28

# UK FACTORY ACCEPTANCE TEST LOG #7

DATE		TIME		USAGE CODE	OPER CODE	FAILURE DATA			TEST RECORD NO.	COMMENTS	OPERATOR
DA	MO	YR	START			STOP	UNIT OR ELEMENT	SERIAL NO.			
06	10	73	0705	0707		OE				INCORRECT COAXIAL MOUNTED ADAPTER RQ NOT A LEGAL ADDRESS	W. H. H.
06	10	73	0705	0755		DF	2401-03	36000 (M13)		TD 3-1 COMPARE ERROR	W. H. H.
06	10	73	0755	0900		DF	2401-03	36000 (M13)		RECURS ON TD 3-1 FAIL	W. H. H.
06	10	73	0705	0836		DF	7231-02	11086	DF T-10	PROG E3B5 PCM INTERRUPT	W. H. H.
06	10	73	0705	0900		ID	(TD 3-1)			REMOVED TCU #3 FOR INSPECTION (TD 3-1 HAD FRAGMENTS FROM A SHATTERED TAPE 5/10/73 1620 IN COLL.)	W. H. H.
06	10	73	0905	1045	FE	S			S-150	RESUME SEVA WITH TCU 1 AND 2	W. H. H.
06	10	73	0905	0937		DF	7251-09	51992	T-11	STORAGE DATA CHECK CE2/SE7 SDR0	W. H. H.
06	10	73	1045	1050	SU					ADDING TCU #3 WITH NEW TAPE ON TD 3-1	W. H. H.
06	10	73	1050	1055		DF	2401-03	36000	M-13	TD 3-1 SENSE COMPARE ERROR	W. H. H.
06	10	73	1055	1105	SU					RECONFIGURE SEVA	W. H. H.
06	10	73	1105	1405	FE	S			S-150	SEVA IN SCHED. MAINT. MODE	W. H. H.
06	10	73	1105	1126		MF				PRINT CARD IN READER	W. H. H.
06	10	73	1405	1420	SU					RECONFIGURE FOR A-1 MODE	W. H. H.
06	10	73	1420	1500	FE	S			S-150	SEVA IN A-1 MODE	W. H. H.
06	10	73	1420	1500		DF	7251-09	51992	M-14 DF	SE-7 SDR0 CHK.	W. H. H.
06	10	73	1500	2300	UM					WORK ON SE 7 (COULD NOT REWIN WOULD NOT OPERATE)	W. H. H.
06	10	73	1500	1515	FE				S-150	RECONFIGURE SE 7 OUT, SE 3 IN	W. H. H.
06	10	73	1515	2220	FE	S			S-150	RESUME SEVA	W. H. H.
06	10	73	2220	2235	SU					RECONFIGURE SEVA	W. H. H.

24

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION										
MALFUNCTION RECORD					USAGE CODES			OPERATION CODES		
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL
06	10	73	13	W. H. H.	W. H. H.	10/6/73	ST	SYSTEM TEST	DF	DETECTED FAILURE
06	10	73	14	W. H. H.	W. H. H.	10/6/73	FE	FACTORY EXERCISE	PF	PROGRAM FAILURE
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE
							SU	SETUP TIME	XF	EXTERNAL FAILURE
							SM	SCHED. MAINT.	OE	OPERATOR ERROR
							UM	UNSCHED. MAINT.		
							FM	FACT. EXER. MARG.		

APPROVAL:

DATE: 10/9/73


UK FACTORY

# ACCEPTANCE TEST LOG #8

				FAILURE DATA								
DATE	TIME	USAGE	OPER	UNIT OR	SERIAL	TYPE	TEST RECORD	COMMENTS		OPERATOR		
DA	MO	YR	START	STOP	CODE	CODE	ELEMENT	NO.	NO.	NO.		
06	10	73	2235	0630	FE	S				S-150	RESUME SEVA	Wright
07	10	73	2235	0610		DF	7201-02	50051	T-12		CE#2 MACH. CK. INT. DEM DEMS.	Wright
07	10	73	0630	0645	SU						RECONFIGURE SEVA	Wright
07	10	73	0645	1430	FE	S				S-150	RESUME SEVA	Wright
07	10	73	1430	1445	SU						RECONFIGURATION	Wright
07	10	73	1446	2205	FE	S				S-150	RESUME SEVA	Wright
07	10	73	1446	1500		OE					PAN 2 WAS NOT CONFIGURED. -	Wright
07	10	73	1520	1521	SU						ADDED PAN 2 AND CONTINUED	Wright
07	10	73	2205	2220	SU						RECONFIGURE SEVA	Chapman
07	10	73	2220	0105	FE	S				S-150	SEVA IN SCHED. MAINT. MODE	Chapman
08	10	73	0105	0120	SU						RECONFIGURE SEVA	Chapman
08	10	73	0120	0200	FE	DF	7231-02	11086	T-13	S-150	SEVA IN A-1 MODE (E3B5- MACH AREA 155 CLR)	Chapman
08	10	73	0200	0225		S					RERUN PASS 07 5 TIMES OK (T-13)	Chapman
08	10	73	0225	0215		DF	7231-02	11086	T-14		E3B5 PRG. INT.	Chapman
08	10	73	0215	0240		S					RERUN PASS 07 5 TIMES OK (T-14)	Chapman
08	10	73	0240	0520		DF	7231-02	11086	T-15		E3B5 MACH AREA NOT CLEARED.	Chapman
08	10	73	0520	0542		S					RERUN PASS 2-3 5 TIMES OK (T-15)	Chapman
08	10	73	0542	0905	FE	S				S-150	RESUME SEVA - 2 PASSES I/O	Wright
08	10	73	0905	0914	SU						RECONFIGURATION	Wright
08	10	73	0914	1705	FE	S				S-150	RESUME SEVA	Wright
08	10	73	0914	1330		DF	7201-02	50051	T-16		CE#2 MACH. CK. INTERRUPT - PARALLEL	Wright
08	10	73	1330	1410	FE	S					PARALLEL FULL SUM CHK. (64-67) <sup>WITH OTHER ERRORS</sup>	Wright
08	10	73	1410	1575		DF	7201-03	50052	F-17		(RE-RUNS OF T-16 OK) INVALID LOGIC	Wright
											PARALLEL FULL SUM CHK. CE 3	Wright

25

FAILURE TYPE: T-TRANSIENT M-MALFUNCTION										
MALFUNCTION RECORD					USAGE CODES			OPERATION CODES		
DA	MO	YR	NO	OPENED BY	CLOSED BY	DATE	UT	UNIT TEST	S	SUCCESSFUL
							ST	SYSTEM TEST	DF	DETECTED FAILURE
							FE	FACTORY EXERCISE	PF	PROGRAM FAILURE
							ID	IDLE IN ORDER	MF	MATERIAL FAILURE
							SU	SETUP TIME	XF	EXTERNAL FAILURE
							SM	SCHED. MAINT.	OE	OPERATOR ERROR
							UM	UNSCHED. MAINT.		
							FM	FACT. EXER. MARG.		

APPROVAL 

DATE 10/9/77



IBM 9020D/E SYSTEM

UNIT FUNCTIONAL TEST DATA RECORD

TEST NO.	ELEMENT/UNIT
1	CE#1
2	CE#2
3	CE#3
4	CE#4

TEST DATA RECORD NO. U- 001  
 LOCATION U K FACTORY  
 DATE OCT 2 1973  
 TEST SPEC. REF. 5.1.1

TEST CONFIGURATION	CE				IOCE			SE					SE/DE					DAU		PAM			SCU			TCU			SCC	RCU		
	1	2	3	4	1	2	3	1	2	3	4	5	6/1	7/2	8/3	9/4	10/5	1	2	1	2	3	1	2	3	1	2	3	1	1	2	
	1	X						X						X																		
	2		X					X																								
	3			X											X																	
4																																

PROGRAM AND SECTION ID		TEST RESULT	CERTIFICATION
Switch Demonstration	CE#1	<i>success</i>	<i>A. J. Frank</i>
Switch Demonstration	CE#2	<i>success</i>	<i>A. J. Frank</i>
Switch Demonstration	CE#3	<i>success</i>	<i>A. J. Frank</i>
Switch Demonstration	CE#4	<b>N/A</b>	

TEST NO.	MALFUNCTION NO.	RERUN REQ'D	TEST NO.	MALFUNCTION NO.	RERUN REQ'D.
1			3		
2			4		

COMMENTS

APPROVAL *[Signature]*  
 DATE OCT 9 1973

**ATTACHMENT I**

**PAM TWO LEVEL SHARED PRIORITY**

**RPQ F19673**

**TEST DEMONSTRATION**



**CONTENTS**

INTRODUCTION	1
ACCEPTANCE TEST SEQUENCE SCHEDULE - APPENDIX A	A-1
TEST PROCEDURE - APPENDIX B	B-1
SPECIAL INSTRUCTIONS - APPENDIX C	C-1

## INTRODUCTION

This Attachment will outline the procedure for the verification of  
RPQ F19673 - PAM Two Level Shared Priority.

All references in this document made to Appendicies will apply to this  
document only.

APPENDIX A  
ACCEPTANCE TEST  
SEQUENCE SCHEDULE

The following test schedule will be used in conjunction with the procedure listed in Appendix B.

<u>Elements</u>	<u>Description</u>	<u>Appendix "B" Ref.</u>
PAM 1 & 3	Test RPQ F19673	1.0
PAM 1 & 2	Test RPQ F19673	1.0
PAM 2 & 3	Test RPQ F19673	1.0

**APPENDIX B**  
**TEST PROCEDURE**

W

## 1.0 Two Level Shared Priority (RPQ F19673)

The Two Level Shared Priority RPQ will allow a high priority adapter in the secondary PAM to have a higher priority than the low priority adapters of the primary PAM. The priority sequence will be primary PAM high priority, secondary PAM high priority, primary PAM low priority, and finally secondary PAM low priority.

The following procedure will demonstrate the operation of PAM Two Level Shared Priority (RPQ F19673) by first showing operation with the RPQ enabled and then with the RPQ disabled. The card loaded program provided for the demonstration is attempting to write to a high priority secondary PAM 1052 while continuously reading sense information from two low priority primary PAM Teletype adapters.

The equipment required for this demonstration is an IOCE in diagnostic mode with the primary and secondary PAMs configured.

### A. Test Procedure

1. Plug a secondary PAM 1052 adapter to the same address as the highest priority INTI adapter in the secondary PAM (Refer to Appendix C, Instruction 1).
2. Plug the INTI adapter with the highest priority in the secondary PAM to the address vacated by the 1052 adapter in Step 1 (Refer to Appendix C, Instruction 2).
3. Plug the PAM common priority boards in the secondary PAM to accommodate the address changes caused by Steps 1 and 2 (Refer to Appendix C, Instruction 3).

4. Select two Teletype adapters in the Primary PAM and install a jumper on each from location U1-F4B05 to U1-F4D08.
5. Load the card deck provided through the IOCE.
6. When the Wait light comes on, store the new address of the secondary PAM high priority 1052 adapter in register 1 of the IOCE.
7. Store the address of the first primary PAM Teletype adapter (with the jumper installed) in register 2 of the IOCE.
8. Store the address of the second primary PAM Teletype adapter (with the jumper installed) in register 3 of the IOCE.
9. Depress the Interrupt pushbutton.
10. The 1052 will print "START," Carrier Return, and print 112 characters with no noticeable time lost.
11. Install a jumper in the secondary PAM from location B-D3N2D04 to B-D3N2D08. This will disable the RPQ.
12. Reload the card deck provided
13. When the Wait light comes on, repeat Steps 6 through 9.
14. The 1052 will print "START," Carrier Return, and one character. It will then stop for approximately 30 seconds and then complete printing the 112 characters.
15. Return the PAM priority boards and the adapter addresses to the normal address and priority assignments.
16. Repeat this procedure on all possible primary/secondary PAM configurations.

**SPECIAL INSTRUCTIONS**

**APPENDIX C**



### INSTRUCTION 1

NOTE: Refer to page ZV500 of PAM Logic Volume 7 for this instruction.

Plug the 1052 address card located at X-U1A7 as per Chart 5 of ZV500, remembering to ground unused bits for a 1052.

### INSTRUCTION 2

NOTE: Refer to page ZV500 of PAM Logic Volume 7 for this instruction.

Plug the INTI address card located at X-W1A7 as per Chart 1 of ZV500.

### INSTRUCTION 3

NOTE: Refer to page ZT300 in PAM Logic Volume 7 for this instruction.

Locate the correct priority board and line for both adapters, using the known priority or decimal address and referencing page ZT300. The respective priority jumpers should be tagged before relocating to assist in restoring the adapters to their original priorities.

Remove the two jumpers for SEL PA and PRI REQ from the priority board pins for the 1052 adapter.

Remove the two jumpers for SEL PA and PRI REQ from the priority board pins for the INTI adapter.

Relocate the jumpers removed from the 1052 priority pins to the INTI priority pins. Relocate the jumpers removed from the INTI priority pins to the 1052 priority pins.

The 1052 adapter should now have the original address and priority of the INTI adapter (High Secondary) and the INTI adapter should have the address and priority of the 1052 adapter (Low Secondary).

Contract No. FA64WA-5223

IBM 9020D/E DATA PROCESSING SYSTEM  
FACTORY AND FIELD ACCEPTANCE TEST  
CHECK LIST AND SPECIFICATION - AMENDMENT #88  
UNITED KINGDOM 9020 D TRIPLEX SYSTEM  
September, 1973

This information is furnished in accordance with requirements of Contract FA64WA-5223 and is subject to Clause 24 thereof entitled "Reproduction and Use of Technical Data" which provides for its use, reproduction or disclosure by the Government for Government Purposes.

INTERNATIONAL BUSINESS MACHINES CORPORATION

## PREFACE

This amendment, used in conjunction with the documents entitled, "IBM 9020D/E Data Processing System Factory and Field Acceptance Test Check List" and "IBM 9020D/E Data Processing System, Factory and Field Acceptance Test Specification", dated May 6, 1970, hereafter called "Reference Check List" and "Reference Specification", comprises the Acceptance Test Check List and Specifications for the United Kingdom 9020D Triplex System.

The purpose of this amendment is to list the schedule of tests to be performed for the United Kingdom 9020D Triplex Acceptance Test.

## CONTENTS

PREFACE	ii
CONTENTS	iii
INTRODUCTION	1
FACTORY ACCEPTANCE TEST SEQUENCE SCHEDULE - APPENDIX A	A-1
FIELD ACCEPTANCE TEST SEQUENCE SCHEDULE - APPENDIX B	B-1
FACTORY FLOOR DIAGRAM - APPENDIX G	G-1
FIELD FLOOR DIAGRAM - APPENDIX H	H-1

## INTRODUCTION

The Factory Test will be conducted in the IBM Manufacturing Facility at Kingston, New York.

The Field Test will be conducted after installation at the London Air Traffic Control Center, West Drayton, Middlesex, England.

Paragraph numbers used in this amendment correspond to those of the Reference Check List and Reference Specification.

**APPENDIX A**  
**FACTORY ACCEPTANCE TEST**  
**SEQUENCE SCHEDULE**

## 9020D SYSTEM UNIT TESTS

<u>TEST No.</u>	<u>ELEMENT/UNIT</u>	<u>DESCRIPTION</u>	<u>SPEC. REF.</u>
U-001	CE	Switch Demonstration	5.1.1
U-002	IOCE	Switch Demonstration	5.1.2
U-003	SE 1-4	Switch Demonstration	5.1.3
U-004	SE 5-7	Switch Demonstration	5.1.3
U-006	SE 1-4	Timing Demonstration	5.1.4
U-007	SE 5-7	Timing Demonstration	5.1.4
U-013	SC	Switch Demonstration	5.1.7
U-014	SC	Interface Demonstration	5.1.7
U-017	PAM	Switch Demonstration	5.1.9
U-018	DASF	Switch Demonstration	5.1.10
U-019	TCU	Switch Demonstration	5.1.11
U-020	I/O Tester 1403	Switch Demonstration	5.1.12
U-021	1052	Switch Demonstration	5.1.13
U-101	CE 1	Functional Test	5.2.1
U-102	CE 2	Functional Test	5.2.1
U-103	CE 3	Functional Test	5.2.1
U-105	CE/SE	ATR Test	5.2.1
U-106	IOCE 1	Selector Channel Functional Test	5.2.2
U-107	IOCE 2	Selector Channel Functional Test	5.2.2
U-108	IOCE 3	Selector Channel Functional Test	5.2.2
U-109	DASF 1	Functional Test	5.2.2
U-110	DASF 2	Functional Test	5.2.2



9020 SYSTEM UNIT TESTS

<u>TEST NO</u>	<u>ELEMENT/UNIT</u>	<u>DESCRIPTION</u>	<u>SPEC. REF</u>
U-111	DASF 3	Functional Test	5.2.2
U-112	TCU #1	Functional Test	5.2.2
U-114	TCU #2	Functional Test	5.2.2
U-116	TCU #3	Functional Test	5.2.2
U-118	DASF	Two Channel Switch Test	5.2.2
U-119	TCU	Dual Interface Tests	5.2.2
U-123	IOCE 1	Multiplexor Channel Functional Test	5.2.3
U-124	IOCE 2	Multiplexor Channel Functional Test	5.2.3
U-125	IOCE 3	Multiplexor Channel Functional Test	5.2.3
U-126	SE 1-3	Functional Test	5.2.4
U-127	SE 4-6	Functional Test	5.2.4
U-128	SE 7	Functional Test	5.2.4
U-133	SC	Functional Test	5.2.6
U-135	PAM	Functional Test	5.2.8
U-136	PAM	Dual Interface Tests	5.2.8
U-137	2821	Functional Test 1403	5.2.9
U-138	2821	Two Channel Switch Test	5.2.9
U-139	1052	Functional Test	5.2.10
U-142	IOCE 1	Diag. Mode Functional Demonstration	5.2.12
U-143	IOCE 2	Diag. Mode Functional Demonstration	5.2.12
U-144	IOCE 3	Diag. Mode Functional Demonstration	5.2.12
U-145	IOCE	I/O Processor Operation Demonstration	5.2.13
U-146	CE/IOCE/SE	Log-Out Demonstration	5.2.14

9020 SYSTEM UNIT TESTS

<u>TEST NO</u>	<u>ELEMENT/UNIT</u>	<u>DESCRIPTION</u>	<u>SPEC. REF.</u>
U-147	IOCE	FET Functional Test	5.1.15
U-148	CE	FLT Functional Test	5.1.15

SYSTEM TEST

<u>TEST NO.</u>	<u>ELEMENT/UNIT</u>	<u>DESCRIPTION</u>	<u>SPEC. REF.</u>
S-001	System	Reconfiguration Test A	6.1.1
S-002	System	Reconfiguration Test B	6.1.2
S-003	System	Reconfiguration Test B	6.1.2
S-004	System	Reconfiguration Test B	6.1.2
S-006	System	Reconfiguration Test C	6.1.3
S-007	System	Reconfiguration Test D	6.1.4
S-120	System	Eight Time Sample Problems	6.3.1
S-123	System	360-9020 Compatibility	6.3.4
S-124	System	360 Mode Recall Test	6.3.5
NOTE 1	System	PAM Two Level Shared Priority	
S-131	System	Power Interlock Test	7.1.1
S-132	System	Test State - Power On/Off	7.1.2
S-133	System	MPO Switch Test	7.1.3
S-134	CE/IOCE/SE	Abnormal Power Loss and Battery Recharge	7.2
S-135	System	Thermal Warning and Protection	7.3
S-136	System	Over Voltage	7.4.1
S-137	System	Over Current	7.4.2
S-138	System	Under Voltage	7.4.3
S-150	System	Factory Acceptance Exercise	8.0
S-160	System	System EPO	7.6

NOTE 1 The PAM Two Level Shared Priority test procedure is defined in Attachment I to this Amendment

**APPENDIX B**  
**FIELD ACCEPTANCE TEST**  
**SEQUENCE SCHEDULE**

9020D SYSTEM UNIT TESTS

<u>TEST NO.</u>	<u>ELEMENT/UNIT</u>	<u>DESCRIPTION</u>	<u>SPEC. REF.</u>
U-001	CE	Switch Demonstration	5.1.1
U-002	IOCE	Switch Demonstration	5.1.2
U-003	SE 1-4	Switch Demonstration	5.1.3
U-004	SE 5-7	Switch Demonstration	5.1.3
U-006	SE 1-4	Timing Demonstration	5.1.4
U-007	SE 5-7	Timing Demonstration	5.1.4
U-013	SC	Switch Demonstration	5.1.7
U-014	SC	Interface Demonstration	5.1.7
U-017	PAM	Switch Demonstration	5.1.9
U-018	DASF	Switch Demonstration	5.1.10
U-019	TCU	Switch Demonstration	5.1.11
U-020	I/O Tester 1403	Switch Demonstration	5.1.12
U-021	1052	Switch Demonstration	5.1.13
U-101	CE 1	Functional Test	5.2.1
U-102	CE 2	Functional Test	5.2.1
U-103	CE 3	Functional Test	5.2.1
U-105	CE/SE	ATR Test	5.2.1
U-106	IOCE 1	Selector Channel Functional Test	5.2.2
U-107	IOCE 2	Selector Channel Functional Test	5.2.2
U-108	IOCE 3	Selector Channel Functional Test	5.2.2
U-109	DASF 1	Functional Test	5.2.2
U-110	DASF 2	Functional Test	5.2.2

9020D SYSTEM UNIT TESTS

<u>TEST NO.</u>	<u>ELEMENT/UNIT</u>	<u>DESCRIPTION</u>	<u>SPEC. REF.</u>
U-111	DASF 3	Functional Test	5.2.2
U-112	TCU #1	Functional Test	5.2.2
U-114	TCU #2	Functional Test	5.2.2
U-116	TCU #3	Functional Test	5.2.2
U-118	DASF	Two Channel Switch Test	5.2.2
U-119	TCU	Dual Interface Tests	5.2.2
U-123	IOCE 1	Multiplexor Channel Functional Test	5.2.3
U-124	IOCE 2	Multiplexor Channel Functional Test	5.2.3
U-125	IOCE 3	Multiplexor Channel Functional Test	5.2.3
U-126	SE 1-3	Functional Test	5.2.4
U-127	SE 4-6	Functional Test	5.2.4
U-128	SE 7	Functional Test	5.2.4
U-133	SC	Functional Test	5.2.6
U-135	PAM	Functional Test	5.2.8
U-136	PAM	Dual Interface Tests	5.2.8
U-137	2821	Functional Test 1403	5.2.9
U-138	2821	Two Channel Switch Test	5.2.9
U-139	1052	Functional Test	5.2.10
U-142	IOCE 1	Diag. Mode Functional Demonstration	5.2.12
U-143	IOCE 2	Diag. Mode Functional Demonstration	5.2.12
U-144	IOCE 3	Diag. Mode Functional Demonstration	5.2.12
U-145	IOCE	I/O Processor Operation Demonstration	5.2.13
U-146	CE/IOCE/SE	Log-Out Demonstration	5.2.14

9020D SYSTEM UNIT TESTS

<u>TEST NO.</u>	<u>ELEMENT/UNIT</u>	<u>DESCRIPTION</u>	<u>SPEC. REF.</u>
U-147	IOCE	FLT Functional Test	5.2.15
U-148	CE	FLT Functional Test	5.2.15

SYSTEM TEST

<u>TEST NO.</u>	<u>ELEMENT/UNIT</u>	<u>DESCRIPTION</u>	<u>SPEC. REF.</u>
S-001	System	Reconfiguration Test A	6.1.1
S-002	System	Reconfiguration Test B	6.1.2
S-003	System	Reconfiguration Test B	6.1.2
S-004	System	Reconfiguration Test B	6.1.2
S-006	System	Reconfiguration Test C	6.1.3
S-007	System	Reconfiguration Test D	6.1.4
S-101	System	SEVA	6.2.1
S-122	System	FLT Practical Test	6.3.3
S-124	System	360 Mode Recall Test	6.3.5
S-131	System	Power Interlock Test	7.1.1
S-132	System	Test State-Power On/Off	7.1.2
S-133	System	MPO Switch Test	7.1.3
S-134	CE/IOCE/SE	Abnormal Power Loss and Battery Recharge	7.2
S-135	System	Thermal Warning and Protection	7.3
S-136	System	Over Voltage	7.4.1
S-137	System	Over Current	7.4.2
S-138	System	Under Voltage	7.4.3
S-139	System	System Main Line Power Loss	7.5
S-140	System	System Main Line Power Loss	7.5
S-141	System	System Main Line Power Loss	7.5
S-160	System	System EPO	7.6



APPENDIX G

FACTORY FLOOR DIAGRAM

(To be supplied at a later date)

**APPENDIX H**

**FIELD FLOOR DIAGRAM**

**(To be supplied at a later date)**