

# intel® Technical Advisory

TA-0745-01

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

January 18, 2005

## Missing Power Cable in Tape Drive Kit for Intel Server Chassis SR2400

*Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The SR2400 may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.*

### Products Affected

ADRTAPEKIT – MM# 856359

### Description

Intel has identified that some Intel Server Chassis SR2400 Tape Drive Accessory kits (ADRTAPEKIT ), with a manufacturing pack date of 14 Sept 04 or earlier, were assembled and shipped with no Tape Drive Power Cable. The cable is used to direct power from either a SCSI or SATA Backplane to the Tape Drive.



The manufacturing Pack Date can be found on the white product label affixed to the kit's outer packaging.

### Workarounds

An off the shelf power extension cable connected to the 4-pin power supply power cable labeled P5 can be used to power a tape drive.

### Corrective Action / Resolution

All product with a manufacturing Pack Date of 15 Sept 04 or later have either been reworked or originally assembled to include the missing cable.

Customers that find that they have Tape Drive Kits with the missing power cable should get replacement product using the standard RMA process.

# intel<sup>®</sup> Technical Advisory

TA-0745-01

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

January 18, 2005

---

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division  
Intel Corporation