

# intel® Action Alert

AA-0747-2 (Update)

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

February 10, 2005

## Intel® Server Board SE7520BD2 – Heat Sink Fastener Pins Not Fully Inserted


Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The Intel® Server Board SE7520BD2 may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

### Products Affected

SE7520BD2 –	SE7520BD2 SATA
SE7520BD2SCSI –	SE7520BD2 SCSI
SE7520BD2V –	SE7520BD2 VALUE
BBDVBB –	SE7520BD2 VALUE OEM 10 Pack
BBDBBSATA –	SE7520BD2 SATA OEM 10 Pack
BBDBBSCSI –	SE7520BD2 SCSI OEM 10 Pack
SC5300BD2 –	SE7520BD2V/SC5300BRP
SC5300BD2NA –	SE7520BD2V/SC5300BRP with North American power cable

### Description

Intel has recently been made aware of an issue with some SE7520BD2 server boards where a heat sink retention pin was found disengaged causing the affected heat sink to move from its required position.




# intel<sup>®</sup> Action Alert

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

AA-0747-2 (Update)

February 10, 2005

As shown in the following photograph, the Intel Server Board SE7520BD2 has two on-board heat sinks that may be affected by this issue.



Note: SATA only versions, of the SE7520BD2, will only have one affected heat sink. The upper heat sink as pictured above.

## Root Cause

Through factory process inspection, Intel has determined that inconsistent pressure was being used to insert the heat sink retention pins from one board to the next. Retention pins that were not fully inserted into the baseboard did not have their tabs fully expanded allowing for potential disengagement during shipping due to excessive shock or vibration.

## Corrective Action / Resolution

For affected products stocked in its warehouses the week of January 17, 2005, Intel has inspected, and where necessary reworked, all boards. All new builds starting from January 18<sup>th</sup>, 2005 and going forward will have heat sinks mounted using a new process including an end of line visual inspection. Boards assembled with the new process will have a serial number starting at BZBD504xxxxx.

# intel<sup>®</sup> Action Alert

AA-0747-2 (Update)

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

February 10, 2005

## Recommended Customer Action

Through continued investigation, Intel has gathered data showing that boards that fall within a serial number range of BZBD448xxxxx thru BZBD451xxxxx had a higher percentage of occurrence for this issue than boards that fall outside of this serial number range.

Intel recommends that customers with in-house inventories that fall within the specified board serial number range visually screen for possible heat sink pin disengagement and manually check that all heat sink pins are fully engaged. Based on the visual screen results, Intel recommends the following:

- 1) If a heat sink is found to be fully removed from the baseboard, Intel recommends that the board be returned using the standard RMA process. These boards have a potential of other component damage due to heat sink contact during shipping.
- 2) If a single heat sink retention pin has disengaged and the heat sink has pivoted from its normal position, Intel recommends that the components around the affected heat sink be visually inspected for damage. If no damage is found, the heat sink can be moved back to its normal position and the loose pin pushed down into place far enough to have its tabs spread open under the baseboard. If component damage is found, the board should be returned using the standard RMA process.
- 3) If a heat sink pin has disengaged but the heat sink is still in its normal position over the chip, Intel recommends that the pin be pushed back down far enough to have its tabs spread open underneath the baseboard.

Note: Board Serial numbers can be found on the white Product Label on the outside of the shipping box, or on a white label affixed to the baseboard on the board edge next to the IMM Connector.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division  
Intel Corporation