Table of Affected Software:

Patch to address SSLv2 rollback issue, plus OpenSSL 0.9.6m update (17 November 2005)

Disclaimer

The following table lists the HP web-based management tools and utilities provided by the deliverables indicated below, and highlights any required updates or other actions in relation to the described patch.

Software versions provided with the following deliverables:

- **HP SmartStart v7.20**
- **HP Management CD v7.20**
- **HP ProLiant Support Pack v7.20**

Agent/Utility	Platform	Operating System	Product Version / Recommended Action
HP Server Management Application and Agents	ProLiant, Prosignia servers, and AlphaServers	Windows 2000 Windows 2003	7.20 / No action needed
		Windows NT 4.0	Upgrade to latest NT 4.0 PSP and then apply update SP31652
		Linux	7.20 / No action needed
HP Version Control Agent	ProLiant Servers	Windows 2000 Windows 2003	2.1.0 / No action needed
		Windows NT 4.0	Upgrade to latest NT 4.0 PSP and then apply update SP31652
		Linux	2.1.0 / No action needed
HP Version Control Repository Manager	ProLiant Servers	Windows 2000 Windows 2003	2.1.0 / No action needed
		Windows NT 4.0	Upgrade to latest NT 4.0 PSP and then apply update SP31652
Compaq Insight Manager 7 (SNMP and DMI agents)	ProLiant and Prosignia servers	Windows 2000 Windows 2003	Upgrade to HP Systems Insight Manager
		Windows NT 4.0	Upgrade to latest IM7 supporting NT 4.0 and apply update SP31652

		Windows 2000	7.20 / No action needed
HP Array Configuration Utility	ProLiant Servers	Windows 2003	
		Windows NT 4.0	Upgrade to latest NT 4.0 PSP and then apply update SP31652
		Linux	7.0 / No action needed
HP Diags	ProLiant Servers	Windows	7.0 / No action needed
		Linux	7.0 / No action needed
HP ADU	ProLiant Servers	Windows	7.20 / No action needed
		Linux	7.20 / No action needed
Compaq Survey Utility (when installed as an agent)	ProLiant and Prosignia servers	Windows NT	Install HP Diagnostics 7.0 or Later (replaces Survey utility)
Performance Management Pack	ProLiant Servers	Windows	3.1 / Apply update SP31652 for all versions
ProLiant Performance Analyzer	ProLiant Servers	Windows	Apply update SP31652 for all versions
Intelligent Cluster Administrator	ProLiant Servers	Windows	Apply update SP31652 for all versions
Compaq Power Management	ProLiant Servers	Windows	Apply update SP31652 for all versions