intel®Technical Advisory

TA-649-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

April 10, 2003

Intel® Server Board SE7501CW2 fan monitoring using LANDesk* Client Manager

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The **Intel Server Board SE7501CW2** *may contain design defects or errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.*

Products Affected

Prod Code	MM#	UPC
SE7501CW2	852945	73585816038
BCW533BB	852948	735858160292

Description
LANDesk Client Manager 6.3 build 211 is not monitoring system fans 3, 4, and 5 and CPU fans 1 and 2.

Root Cause
The Intel Server Board SE7501CW2 Resource CD (part # C29966-003) does not contain the correct LANDesk Client Manager registry file to monitor all fans.

Corrective Action / Resolution
An updated version of LANDesk Client Manager registry file is located at:
http://support.intel.com/support/motherboards/server/se7501cw2/. To locate the file, (1) click on "Software & Drivers" link in the left navigation bar, (2) choose Windows* 2000 and click <GO>, and (3) locate the file SE7501CW2_LDCM_fan_regfile.exe.

Follow the instructions in the readme.txt file to install and use this registry file.

Please refer to the http://support.intel.com/support/motherboards/server/se7501cw2/ site for updates to the LANDesk Client Manager software.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms and Services Division
Enterprise Platforms Group
Intel Corporation