

StorageWorks ESL9595L1 Library Configuration Guide

ESL9322 library with Ultrium 230 drives

301927-B22	ESL9322L1 222 slot 2 Ultrium 230 drives
301927-B28	ESL9322L1 222 slot 8 Ultrium 230 drives
301928-B22	ESL9322L1 322 slot 2 Ultrium 230 drives
301928-B28	ESL9322L1 322 slot 8 Ultrium 230 drives

Add-on drive supported

301930-B21	ESL9000 Add-on Ultrium drive
------------	------------------------------

Power Cords Supported

146210-001	ESL9000 Power cords pair, US/CANADA/MEX* <i>*(shipped with all units)</i>
146210-AR1	ESL9000 Power cord pair, SE ASIA/INDIA
146210-021	ESL9000 Power cord pair, CENTRAL EUROPE
146210-011	ESL9000 Power cord pair, AUS/CHINA/NZL
146210-111	ESL9000 Power cord pair, SWITZERLAND
146210-031	ESL9000 Power cord pair, UK/HONG KONG
146210-061	ESL9000 Power cord pair, ITALY
146210-081	ESL9000 Power cord pair, DENMARK
146210-291	ESL9000 Power cord pair, JAPAN

NOTE: Order Local power cords separately, supplied from regions

DAS connection: Controllers supported

HP9000 servers

A5149A U2 LVD single port
A5150A U2 LVD dual port
A6828 U3 LVD single port
A6829 U3 LVD dual port
A4999A LVD single port

HP Netserver

Adaptec AHA 29160
Adaptec AHA 39160

HP ProLiant Servers

129803-B21, 66MHz Ultra 3 LVD, dual channel controller
154457-B21 Ultra 3 LVD, single channel controller

FC Controllers supported

HP9000 servers

A5158A 1G FC
A6795A 2G FC

HP Netserver

D8602B 1G FC

SAN connection: FC to SCSI routers supported

262665-B21 Embedded Data Router, ESL 9000 embedded fibre option e2400 – Base
262664-B21 Embedded Data Router, ESL 9000 embedded fibre option e2400 – Upgrade



Pre-sales site survey is required, document available on http://www.compaq.com/support/techpubs/installation_guides/146587-001.html

StorageWorks ESL9322L1 Library Configuration Guide

OS Supported

Windows NT 4.0, Windows 2000
Tru64 Unix 4.0G, 5.1 and 5.1A, (TruCluster)
Linux Redhat 7.1 and 7.2
SUSE Linux 7.2

ISV Software Applications Supported

VERITAS Backup Exec™ 8.6
CA BrightStor ARCserve2000™ for NT/2000
Legato NetWorker v6.1.2
VERITAS NetBackup v3.4.3, v4.5

Automation and Network Utilities Supported

HP Insight Manager v
HP Tape Storage Management Console
MRU (Media robot utility)

For the ISV/OS support matrix refer to the Tape automation compatibility matrix on

<http://www.compaq.com/storage/tapelibrarymatrix.html>

Cables Supported:

341176-B21 SCSI Cable, VHDCI / Wide, 6 ft
341177-B21 SCSI Cable, VHDCI / Wide, 12 ft
201160-B21 SCSI Cable, VHDCI / Wide, 10 m
201160-B23*SCSI Cable, VHDCI / W, 20 m
*Requires LVD SCSI extender 221249-B21, Check connectors on library and HBA/Router before ordering cables

Servers Supported

HP ProLiant Servers:

ProLiant DL760
ProLiant ML750
ProLiant DL580/G2
ProLiant ML 570

HP-UX servers:

Superdome
rp8400
rp7400 (N class)
rp5400 series (L Class)
rp2450/2470 (A class)

K class
D Class

HP Netserver

HP lxr8500
HP lh6000
HP lh6000r
HP lt6000r

Media/Label Supported

C7971A HP Ultrium data cartridge
C7978A HP Ultrium universal cleaning cartridge
C7970B HP Ultrium Barcode labels, 100 pack



StorageWorks ESL9322L1 Library Configuration Guide

Standard Warranty: One year,
on-site next business day service

Installation SKUs

FM-E7INS-IN 309172-002 INSTALL
ESL9000 library 0-8 Drives

Capacity Upgrade Technology SKUs

293588-B21 ESL9322, slot upgrade 222 TO
322 slots*

*Serial number of your existing library is required
when ordering these capacity upgrade SKUs,

ESL9000 warranty upgrade options:

FM-E74HR-12	309164-002	1Y 9X5/4HR ESL 0-8 DR 1Y WAR
FM-E74HR-36	309165-002	3Y 9X5/4HR ESL 0-8 DR 1Y WAR
FM-E74HR-60	309166-002	5Y 9X5/4HR ESL 0-8 DR 1Y WAR
FM-E7724-12	309167-002	1Y 24X7/4HR ESL 0-8 DR 1Y WAR
FM-E7724-36	309168-002	3Y 24X7/4HR ESL 0-8 DR 1Y WAR
FM-E7724-60	309169-002	5Y 24X7/4HR ESL 0-8 DR 1Y WAR
FM-E7XHW-36	309170-002	3Y 9X5/ND ESL 0-8 DR 1Y WAR
FM-E7XHW-60	309171-002	5Y 9X5/ND ESL 0-8 DR 1Y WAR