

Home | News | Products | Services | Solutions | About IBMShopIBM Support Download

in

Support Home

IBM NetVista thin client

Overview
How to Buy
Support

Select a Language
Online Assistant

Warranty Status Lookup

Technical Information

Downloadable files
Hints and tips
Hot news
Online publications
Parts information
Product information

Quick Path

Survey

NetVista N2200w (8363Wxx) - Information index and problem status

Applicable Countries

Worldwide

Service Hints & Tips

Information

Click any of the following items to access information about NetVista N2200w features, online publications, service pack downloads, and available online support.

- [Features](#)
- [Publications](#)
- [Service pack downloads](#)
- [Service pack details](#)
- [Software service and support](#)
- [Hardware technical support](#)

NOTE: The support structure for the NetVista N2200w differs from the support structure for Network Station Manager.

Problems fixed, known problems, and limitations

- [Service Pack 2.0 - Problems fixed](#)
- [Service Pack 2.0 - Known problems and workarounds](#)
- [Service Pack 2.0 - Limitations and workarounds](#)
- [Service Pack 1.1 - Problems fixed](#)
- [Service Pack 1.1 - Known problems and workarounds](#)
- [Service Pack 1.1 - Limitations and workarounds](#)
- [Service Pack 1.0 - Problems fixed](#)
- [Service Pack 1.0 - Limitations, known problems, and workarounds](#)
- [Service Pack 0.5 - Problems fixed](#)
- [Service Pack 0.5 - Limitations, known problems, and workarounds](#)

Problems fixed in Service Pack 2.0

- [Ctrl key remapping](#)
- [Enter key remapping](#)
- [Euro key does not work in FutureSoft emulators](#)
- [Exiting preferences tab](#)
- [UNIX connection slow when booting DHCP](#)
- [Slow DHCP connections to RDP servers](#)
- [DHCP client does not renew its lease](#)
- [Ctrl+Alt+Home does not launch default connection](#)
- [Migration to SP 1.1 may cause administrator password set in NS Boot code](#)
- [Newest Belkin adapters not supported](#)

Known problems and workarounds - Service Pack 2.0

As of Service Pack 2.0, the following list of problems have been identified. Click any item on the list to access a document which provides a detailed problem description, a workaround if one is available, and information about the status of the problem.

- [Citrix Virtual Comm not supported](#)
- [Low bitrate video windows appear with right side cut off](#)
- [Upper case characters in Microsoft Word on Microsoft Windows 2000 with RDP](#)
- [Unable to get into properties after changing the emulator session title](#)
- [Media Player resize and volume controls not supported](#)
- [RDA server not supported with Internet Explorer modem autodial](#)
- [Operating System update via modem](#)
- [Configuration update is merge not clone](#)
- [DHCP unable to obtain an IP address](#)
- [Illegal Operations error during boot PROM update](#)
- [Citrix dial-in support](#)
- [IBM Multi-port USB hub support](#)

HelpCenter Phone List

[Worldwide Support](#)

[Privacy](#) | [Legal](#) | [Contact](#)